

SIEMENS

January 17, 1997
HDC:97:009

Document Control Desk
Attn: Chief, Planning, Program and Management Support Branch
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-0001

Errata for EXEM/PWR Large Break LOCA ECCS Model Update, XN-NF-82-20(P), Revision 1, Supplement 6


Ref.: 1. EXEM/PWR Large Break LOCA ECCS TOODEE2 Updates, XN-NF-82-20(P), Revision 1, Supplement 6, December 1996.

Enclosed are fifteen (15) copies of an attachment to this letter which includes errata to EXEM/PWR Large Break LOCA ECCS Model Update, XN-NF-82-20(P), Revision 1, Supplement 6 topical report which is under review by the NRC. The errata are for the most part typographical errors and are not technical in nature. If these errata are acknowledged during the NRC review of the reference topical report, these errors would be corrected in the NRC approved version of the topical report prior to creating the "A" version of the report.

The information contained in the enclosed attachment is considered to be proprietary to Siemens Power Corporation and is considered protected by the affidavit previously supplied to the NRC with the reference topical report.

If you have any questions or if I can be of further assistance, please call me at (509) 375-8563.

Very truly yours,



H. Donald Curet, Manager
Product Licensing

/smg

Enclosures

cc: Mr. E. Y. Wang (USNRC)

9701290112 970117
PDR TOPRP EMVEXXN
C PDR

Siemens Power Corporation

Nuclear Division
Engineering & Manufacturing

2101 Horn Rapids Road
P.O. Box 130
Richland, WA 99352-0130

Tel: (509) 375-8100
Fax: (509) 375-8402

10071
20-B-2
Exxon

TOPRP