



Northeast
Utilities System

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 128
Waterford, CT 06385-0128
(203) 447-1791

January 17, 1997
Docket No. 50-336
B16159

Re: 10 CFR 50.73(a)(2)(i)
10 CFR 50.73(a)(2)(ii)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

This letter forwards Licensee Event Report (LER) 96-042-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on December 18, 1996. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i) and 10 CFR 50.73(a)(2)(ii).


The following are NNECO's commitments made within this letter. All other statements made within this letter are for information only.

B16159-01: Engineering will implement corrective actions to either upgrade the non-QA components to QA or install permanent electrical isolation devices within the RM-8123A/B and RM-8262A/B instrument loops.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

9701290122 970117
PDR ADOCK 05000336
S PDR



J. A. Price
Director - Millstone Unit No. 2

cc: see Page 2

IF 22/1

Attachment: LER 96-042-00

cc: W. D. Travers, Director of Special Projects
H. J. Miller, Region I Administrator
D. P. Beaulieu, Senior Resident Inspector (Acting), Millstone Unit No. 2
D. G. McDonald, Jr., NRC Project Manager, Millstone Unit No. 2