

Detroit  
Edison

Douglas R. Gipson  
Senior Vice President  
Nuclear Generation

Fermi 2  
6400 North Dixie Highway  
Newport, Michigan 48166  
(313) 586-5249

10CFR50.73

January 23, 1997  
NRC-97-0012

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Reference: Fermi 2  
NRC Docket No. 50-341  
NRC License No. NPF-43

Subject: Licensee Event Report (LER) No. 96-023


Pursuant to 10CFR50.73, Detroit Edison is submitting the enclosed LER No. 96-023 documenting a reportable event that occurred on December 24, 1996 which involved a Technical Specification required shutdown due to a Drywell to Suppression Chamber Vacuum Breaker that failed to indicate a fully closed position.

The following specific commitment is being made in this LER:

The section on magnet installation in the vacuum breaker maintenance procedure will be revised prior to the next refueling outage or maintenance on a vacuum breaker to include assembly details that will prevent recurrence of this event.

If you have any questions, please contact Mari Jaworsky, Compliance Engineer, at (313) 586-1427.

Sincerely,



cc: A. B. Beach  
M. J. Jordan  
A. J. Kugler  
N. O'Keefe  
M. V. Yudas, Jr.  
Region III  
Wayne County Emergency Management Division

IE22%

9701290175 970123  
PDR ADOCK 05000341  
S PDR