



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

C. M. Moseley
Dir. Div. V
Program Development
SALP I 20

January 20, 1981

Docket No. 50-546

Docket No. 50-547

→ MEMORANDUM FOR: N. C. Moseley, Director, Division of Program
Development and Appraisal

FROM: James G. Keppler, Director

SUBJECT: SALP BOARD RESULTS FOR MARBLE HILL NUCLEAR
GENERATING STATION, UNITS 1 AND 2 - DECEMBER 1980

The Systematic Assessment of Licensee Performance Board (SALP) for Marble Hill Units 1 and 2 has decided not to rate the performance of the licensee, as they were shut down under an IE Order for 10.5 months during this evaluation period. The Board recommended that the present increased frequency of inspections be continued until the licensee has adequately demonstrated the implementation of his QA program.

A management meeting was held at the Marble Hill site on December 9, 1980.

The results of the SALP evaluation, the recommended plan of action for Region III, and the report covering the meeting with the licensee are enclosed for your use.

James G. Keppler
James G. Keppler
Director

Enclosures: As Stated

cc w/encl:

J. S. Snizek

J. N. Willson, PM, NRR
Regional Directors

8508150494 850610
PDR FOIA
LEIGHT084-293 PDR

Ed Schwabing
w. L. H.

FOIA-94-293
K/76