



**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 409 838-6631

November 4, 1985  
RBG-22555  
File Code: G9.5, G9.20.8

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Denton:

River Bend Station - Unit 1  
Docket No. 50-458

Gulf States Utilities Company provides the attached information concerning seismic qualification and general maintenance practices as requested in a letter dated November 1, 1985 from Dr. Walter R. Butler to Mr. William J. Cahill. If additional information is required, please contact Mr. Rick King at (504) 635-6995.

Sincerely,

*J. E. Booker*

J. E. Booker  
Manager-Engineering  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

JEB/TFP/ADK/RJK/meh

Attachment

8511110291 851104  
PDR ADDCK 05000458  
PDR

Boo!  
11

ATTACHMENT

RESPONSE TO  
REQUEST FOR ADDITIONAL INFORMATION

GSU is instructing its maintenance personnel and amending its general maintenance practices at River Bend Station on the following items:

- (a) Check for missing or loose screws before returning any safety-related equipment items to service following any repair or maintenance.
- (b) Loose materials such as tamper proof bars over the set point adjustments on instrumentation and control panels should not be placed on top of the cabinets, but should be stored in a manner that prevents any harmful interaction with safety system.
- (c) A record of the implementation of the instructions to perform the checks on missing screws and proper storage of loose materials are to be kept in an auditable manner.