



Carolina Power & Light Company

85 OCT 31 A10:53  
ROBINSON NUCLEAR PROJECT DEPARTMENT  
POST OFFICE BOX 790  
HARTSVILLE, SOUTH CAROLINA 29550

OCT 28 1985

Robinson File No: 13520

Serial: RNP/85-3875

Dr. J. N. Grace  
Regional Administrator  
United States Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30323

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
10CFR21 SEISMIC SUPPORTS

Dear Dr. Grace:

Carolina Power and Light (CP&L) determined on October 25, 1985, that the event described in Licensee Event Report (LER) 85-06 is reportable per 10CFR21. Seismic supports were declared inoperable based on the requirements of IE Bulletin 79-02. LER-85-06, dated February 14, 1985, is considered to meet all the reporting requirements to the NRC per 10CFR21. Additional information on this event may be obtained from CP&L's March 14, 1985 response to the violation issued in Inspection Report 85-06. This determination was delayed due to a parallel evaluation being conducted by the Architect Engineer involved in the event. A CP&L Corporate Officer has been notified of this 10CFR21 determination.

If you should need any additional information, please contact Mr. J. M. Curley at 803-383-4524, extension 2367.

Very truly yours,

R. E. Morgan  
General Manager  
H. B. Robinson S. E. Plant

CLW:ac

cc: J. M. Taylor (3)

8511110300 851028  
PDR ADOCK 05000261  
S PDR

1/0  
IE 19