



October 25, 1994

L-94-269  
10 CFR 73.71

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Re: St. Lucie Units 1 and 2  
Docket Nos. 50-335 and 50-389  
Safeguards Event Log Entries  
Third Quarter 1994

Pursuant to 10 CFR 73.71(c)(2), Florida Power and Light Company is submitting a copy of St. Lucie Plant Safeguards Event Log Entries for the period July 1, 1994 to September 30, 1994.

The enclosed material does not contain safeguards information as defined by 10 CFR 73.21.

Very truly yours,

*D. A. Sager*  
D. A. Sager  
Vice President  
St. Lucie Plant

DAS/CDW

Enclosure

cc: Stewart D. Ebnetter, Regional Administrator, USNRC Region II  
Senior Resident Inspector, USNRC, St. Lucie Plant

2-11-97 XA

Duke

9410310332

Spt XA

GF

*[Handwritten signature]*  
11

11/7

**FLORIDA POWER & LIGHT**

**ST. LUCIE PLANT**

QUARTERLY EVENT LOG

THIRD QUARTER 1994

July 1, 1994 through September 30, 1994

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
03-94/001	07-01-94/1700	07-01-94/1205	Card Key (CK) # 2568 lost on site.	Human Error	CK # 2568 deleted from computer @ 1205. Access history report showed no unauthorized activity. CK found, checked for signs of tampering, with negative results, and reassigned to individual suffering the loss.
03-94/002	07-05-94/1230	07-05-94/0940	CK # 785 lost on site.	Human Error	CK # 785 deleted from computer @ 0940. Access history report showed no unauthorized activity. CK found, checked for signs of tampering, with negative results, and reassigned to individual suffering the loss.
03-94/003	07-06-94/0900	07-06-94/0744	CK # 2460 lost off site.	Human Error	CK # 2460 deleted from computer @ 0744. Access history report showed no unauthorized activity.
03-94/004	07-11-94/0802	07-11-94/0759	Smart Door Module (SDM) # 276 inoperative.	Hardware Failure	Security Officer posted @ 0802. Repaired, tested and back in service @ 0811.
03-94/005	07-12-94/0802	07-12-94/0801	PZ-11E CCTV inoperative.	Hardware Failure	PTZ-05 dedicated @ 0801. Repaired, tested, back in service @ 1305.
03-94/006	07-12-94/1202	07-12-94/1153	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1157. Area searched with negative results.
03-94/007	07-18-94/1200	07-18-94/0833	Delivery gate X-Ray inoperative.	Hardware Failure	Compensatory measures in place @ 0833. Repaired, tested, back in service @ 07-19-94/1105.
03-94/008	07-20-94/0615	07-20-94/0600	CK # 2337 lost off site.	Human Error	CK # 2337 deleted from computer @ 0602. Access history showed no unauthorized activity.
03-94/009	07-20-94/1040	07-20-94/0952	CK # 475 Lost on site.	Human Error	CK # 475 deleted from computer @ 0953. Access history showed no unauthorized activity.
03-94/010	07-21-94/1320	07-21-94/1300	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1300. Area searched with negative results.
03-94/011	07-24-94/1500	07-24-94/1326	Electronic Security System (ESS) failure.	Hardware Failure	Compensatory measures in place @ 1334. System operational @ 1359. All required checks made and compensatory measures secured @ 1443. RE: Front End Processor (FEP) failure.
03-94/012	07-27-94/1700	07-27-94/0746	CK # 915 lost off site.	Human Error	CK # 915 deleted from computer @ 0748. Access history report showed no unauthorized activity.
03-94/013	07-28-94/1510	07-28-94/1028	CK # 2148 lost on site.	Human Error	CK # 2148 deleted from computer @ 1028. Access history report showed no unauthorized activity. CK found, checked for signs of tampering, with negative results, and reassigned to individual suffering the loss.
03-94/014	07-28-94/2045	07-28-94/2030	Vital door locking mechanism inoperative.	Hardware Failure	Security Officer posted @ 2030. Repaired, tested, back in service @ 07-29-94/0209.
03-94/015	07-29-94/1610	07-29-94/1548	CK # 289 lost on site.	Human Error	CK # 289 deleted from computer @ 1548. Access history showed no unauthorized activity. CK found, checked for signs of tampering with negative results, and reassigned to individual suffering the loss.
03-94/016	08-03-94/1057	08-03-94/1054	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1057. Area searched with negative results.
03-94/017	08-03-94/1145	08-03-94/1145	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1150. Area searched with negative results.
03-94/018	08-03-94/2219	08-03-94/2219	PZ-11E CCTV inoperative.	Hardware Failure	PTZ-04 dedicated @ 2219. Repaired, tested and back in service @ 08-04-94/0758.
03-94/019	08-03-94/2240	08-03-94/2239	Door to vital area left unsecured.	Human Error	Security Officer posted @ 2240. Area searched with negative results.
03-94/020	08-04-94/0815	08-04-94/0715	CK # 802 lost off site.	Human Error	CK # 802 deleted from computer @ 0715. Access history showed no unauthorized activity.

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
03-94/021	08-04-94/1240	08-04-94/1134	ESS failure	Hardware Failure	Compensatory measures in place @ 1142. System operational. All required checks made and compensatory measures secured @ 1238. RE: FEP and loop failure
03-94/022	08-04-94/1430	08-04-94/1309	Vital door locking mechanism inoperative	Hardware Failure	Security Officer posted @ 1311. Area searched with negative results. Repaired, tested, back in service @ 1429.
03-94/023	08-05-94/1300	08-05-94/1233	PZ-40 Microwave (M/W) stuck in alert due to rain.	Hardware Failure	Security Officer posted @ 1239. Rain subsided, M/W reset, tested, and back in service @ 1348.
03-94/024	08-05-94/1300	08-05-94/1235	PZ-26 M/W stuck in alert due to rain.	Hardware Failure	Security Officer posted @ 1238. Rain subsided, M/W reset, tested and back in service @ 1505.
03-94/025	08-06-94/2140	08-06-94/1701	ESS failure.	Hardware Failure	Compensatory measures in place @ 1709. System operational @ 1835. All required checks made and compensatory measures secured @ 1922. RE: FEP failure and free pool exhausted. place @ 1709.
03-94/026	08-06-94/2155	08-06-94/1624	PZ-40 M/W stuck in alert due to rain.	Hardware Failure	Security Officer posted @ 1627. Rain subsided, M/W reset, tested and back in service @ 2150.
03-94/027	08-07-94/2110	08-07-94/1951	PZ-40 M/W stuck in alert due to rain.	Hardware Failure	Security Officer posted @ 1954. Rain subsided, M/W reset, tested and back in service @ 2215.
03-94/028	08-07-94/2210	08-07-94/1956	PZ-26 M/W constant alarms due to rain.	Hardware Failure	Security Officer posted @ 1957. Rain subsided, M/W reset, tested, and back in service @ 2202.
03-94/029	08-08-94/0758	08-08-94/0757	CK # 814 Lost Off Site	Human Error	CK # 814 deleted from computer @ 0758. Access history showed no unauthorized activity.
03-94/030	08-08-94/1209	08-08-94/1205	Door to Vital Area left Unsecured	Human Error	Security Officer posted @ 1209. Area searched with negative results.
03-94/031	08-08-94/1414	08-08-94/1414	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1414. Rain subsided, M/W reset, tested, and back in service @ 1514.
03-94/032	08-08-94/1830	08-08-94/1759	CK # 2063 Lost off Site.	Human Error	CK # 2063 deleted from computer @ 1759. Access history report showed no unauthorized activity.
03-94/033	08-08-94/1930	08-08-94/1919	Single Imux Failure.	Hardware Failure	Compensatory measures in place @ 1925. IMUX was operational 1921. All tests completed and compensatory measures secured @ 1928.
03-94/034	08-08-94/1950	08-08-94/1950	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1950. Rain subsided, M/W reset, tested and back in service @ 2227.
03-94/035	08-08-94/2100	08-08-94/2033	North Security Building (NSB) entry scans inoperative	Hardware Failure	Compensatory measures in place @ 2033. Repaired, tested and back in service @ 2259.
03-94/036	08-08-94/2300	08-08-94/1955	ESS Failure.	Hardware Failure	Compensatory measures in place @ 2004. System operational @ 2138. All required checks made and compensatory measures secured @ 2236. RE: FEP failure.
03-94/037	08-09-94/0725	08-09-94/0725	Inadvertent attempt to bring a firearm on site.	Human Error	One Contractor Employee's access denied. Investigation revealed no malevolent intent. Individual suspended per plant policy.
03-94/038	08-09-94/1100	08-09-94/1100	Safeguards Document left unattended.	Human Error	Document left unattended and retrieved inside the Protected Area. It could not have assisted in radiological sabotage or theft of SNM.
03-94/039	08-09-94/1700	08-09-94/1607	Single Imux Failure.	Hardware Failure	Compensatory measures in place @ 1615. Area searched with negative results. IMUX was operational 164. All tests completed and compensatory measures secured @ 1705.

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
03-94/040	08-09-94/1923	08-09-94/1750	NSB entry scans inoperative.	Hardware Failure	Compensatory measures in place @1750. Repaired, tested, and back in service @1904.
03-94/041	08-09-94/2010	08-09-94/1750	Single IMUX Failure	Hardware Failure	Compensatory measures in place @ 1755. IMUX was operational @ 1752. All tests completed and compensatory measures secured @ 1757.
03-94/042	08-09-94/2020	08-09-94/1806	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1808. Rain subsided, M/W reset, tested and back in service @ 1902.
03-94/043	08-10-94/1617	08-10-94/1257	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1258. Rain subsided, M/W reset, tested and back in service @ 1551.
03-94/044	08-11-94/1615	08-11-94/0949	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 0949. Rain subsided, M/W reset, tested and back in service @ 1212. <u>Stuck in Intrusion S/O in place</u> <u>Reset, tested, back in service</u> 08-11-94/1324      08-11-94/1325      08-11-94/1413
03-94/045	08-11-94/1616	08-11-94/1324	PZ-26 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1328. Rain subsided and M/W reset, tested and back in service @ 1432.
03-94/046	08-12-94/0130	08-12-94/0118	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 0118. Rain subsided, M/W reset, tested and back in service @ 0207. <u>Stuck in Intrusion S/O in place</u> <u>Reset, tested, back in service</u> 08-12-94/0218      08-12-94/0222      08-12-94/0458
03-94/047	08-12-94/0300	08-12-94/0226	ESS Failure.	Hardware Failure	Compensatory measures in place @ 0232. System operational @ 0308. All required checks made and compensatory measures secured @ 0358. RE: FEP failure (Severe weather).
03-94/048	08-12-94/1545	08-12-94/1539	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1545. Rain subsided and M/W reset, tested and back in service @ 1651.
03-94/049	08-14-94/0306	08-14-94/0305	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 0306. Rain subsided, M/W reset, tested and back in service @ 0333. <u>Stuck in Intrusion S/O in place</u> <u>Reset, tested, back in service</u> 08-14-94/0403      08-14-94/0407      08-14-94/0447 08-14-94/0500      08-14-94/0503      08-14-94/0731
03-94/050	08-14-94/0514	08-14-94/0509	PZ-26 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 0514. Rain subsided, M/W tested back in service @ 0800.
03-94/051	08-14-94/1000	08-14-94/0939	PZ-11E CCTV inoperative.	Hardware Failure	PTZ-04 dedicated @ 0939. CCTV regained, PTZ-04 un-dedicated @ 1021.
03-94/052	08-15-94/1110	08-15-94/1030	Door to Vital Area left Unsecured	Human Error	Security Officer posted @ 1034. Area searched with negative results.
03-94/053	08-15-94/1630	08-15-94/1545	Security Officer inattentive to duties at access console.	Human Error	Security Officer relieved from duty @ 1545. Access history reports indicate no personnel ingress the security building while the Security Officer was inattentive.
03-94/054	08-16-94/1535	08-16-94/0911	Vital door locking mechanism inoperative.	Hardware Failure	Security Officer posted @ 0911. Security was performing operability on door when locking device failed. Repaired, tested, back in service @ 1013.
03-94/055	08-16-94/1912	08-16-94/1912	East Security Building (ESB) south X-RAY inoperative.	Hardware Failure	Compensatory measures in place @ 1912. Repaired, tested and back in service @ 08-17-94/0621.
03-94/056	08-19-94/2333	08-19-94/2209	Door to vital area left unsecured.	Human Error	Security Officer posted @ 2211. Area searched with negative results.
03-94/057	08-22-94/0830	08-22-94/0804	Door to vital area left unsecured.	Human Error	Security Officer posted @ 0807. Area searched with negative results.

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
03-94/058	08-22-94/1807	08-22-94/1804	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1807. Rain subsided, M/W reset, tested and back in service @ 1828.
03-94/059	08-24-94/1532	08-24-94/1315	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1319. Rain subsided, M/W reset, tested and back in service @ 1453.
03-94/060	08-26-94/0400	08-26-94/0356	PZ-40 M/W in constant intrusion alarm due to rain.	Hardware Failure	Security Officer posted @ 0400. Rain subsided, alarm cleared, and back in service @ 0437.
03-94/061	08-26-94/1452	08-26-94/1445	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1452. Area searched with negative results. Repaired, tested, and back in service @ 1547.
03-94/062	08-28-94/1455	08-28-94/1455	PZ-26 M/W in constant intrusion alarm due to rain.	Hardware Failure	Security Officer posted @ 1455. Rain subsided, alarm cleared, and back in service @ 1726.
4/063	08-28-94/1500	08-28-94/1500	PZ-40 M/W in constant intrusion alarm due to rain.	Hardware Failure	Security Officer posted @ 1500. Rain subsided, alarm cleared, and back in service @ 1533. <u>Alarms regenerated</u> <u>S/O in place</u> <u>Back in service</u> 08-28-94/1537      08-28-94/1537      08-28-94/1700
03-94/064	08-28-94/1949	08-28-94/1932	Single IMUX Failure	Hardware Failure	Compensatory measures in place @ 1935. IMUX was operational @ 1935. All tests completed and compensatory measures secured @ 1946.
03-94/065	08-28-94/2228	08-28-94/2145	IMUX Failure (10 and 12)	Hardware Failure	Compensatory measures in place for IMUX 12 @ 2148. IMUX 10 failed @ 2206. Compensatory measures were in place @ 2206. Both IMUX operational @ 2219. All tests completed and compensatory measures secured @ 2226.
03-94/066	08-30-94/1336	08-30-94/0639	CK # 3300 Lost off Site	Human Error	CK # 3300 deleted from computer @ 0640. Access history report showed no unauthorized activity.
03-94/067	08-30-94/1340	08-30-94/1050	CK # 1820 Lost off Site	Human Error	CK # 1820 deleted from computer @ 1052. Access history report showed no unauthorized activity.
03-94/068	09-01-94/0648	09-01-94/0644	Vital door locking mechanism inoperative.	Hardware Failure	Security Officer posted @ 0647. Repaired, tested and back in service @ 0916.
03-94/069	09-02-94/1600	09-01-94/1210	CK # 367 Lost on site	Human Error	CK # 367 deleted from computer @ 1211. Access history report showed no unauthorized activity. CK found, checked for signs of tampering, with negative results, and reassigned to individual suffering the loss.
4/070	09-06-94/0330	09-06-94/0318	Vital door locking mechanism inoperative.	Hardware Failure	Security Officer posted @ 0318. Repaired, tested and back in service @ 0324.
03-94/071	09-06-94/1030	09-06-94/1026	Vital door locking mechanism inoperative.	Hardware Failure	Security Officer posted @ 1030, secured door. Area searched with negative results. Door tested and back in service @ 1036.
03-94/072	09-06-94/1500	09-06-94/1500	CK # 2686 Lost off Site *	Human Error	CK # 2686 turned into Security @ 1500. Access history showed no unauthorized activity. CK checked for signs of tampering with negative results. CK retained in Badging Office for Employee to pick up.
03-94/073	09-07-94/1600	09-07-94/1435	CK # 487 Lost on site.	Human Error	CK # 487 found by Security @ 1435. Access history report showed no unauthorized activity. CK checked for signs of tampering with negative results, and re-assigned to individual suffering the loss.
03-94/074	09-09-94/0700	09-09-94/0640	ESB north X-Ray inoperative.	Hardware Failure	Compensatory measures in place @ 0640. X-Ray reset, tested, back in service and compensatory measures secured @ 0642.
03-94/075	09-12-94/1230	09-12-94/0639	PZ-26 M/W in constant intrusion alarm due to rain.	Hardware Failure	Security Officer posted @ 0640. Rain subsided, alarm cleared, and back in service @ 0711.



LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
03-94/076	09-12-94/1520	09-12-94/1127	PZ-26 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1133. Rain subsided, M/W reset, tested and back in service @ 1321.
03-94/077	09-13-94/0505	09-13-94/0313	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 0313. Rain subsided, M/W reset, tested and back in service @ 0407.
03-94/078	09-13-94/0510	09-13-94/0313	PZ-26 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 0313. Rain subsided, M/W reset, tested and back in service @ 1820.
03-94/079	09-13-94/1130	09-13-94/0846	Single IMUX Failure.	Hardware Failure	Compensatory measures in place @ 0855 for IMUX 13. IMUX 1 inoperative @ 0955. Compensatory measures in place @ 1004. Additional IMUX's went down @ 1015 and compensatory measure for complete system failure in place @ 1025. System operational @ 1706. All required checks made and compensatory measures secured @ 1820.
4/080	09-13-94/1200	09-13-94/0911	PZ-40 M/W in constant intrusion alarm due to rain.	Hardware Failure	Security Officer posted @ 0911. Rain subsided, alarm cleared, and back in service @ 0919.
03-94/081	09-14-94/0818	09-14-94/0818	Delivery Gate X-Ray inoperative.	Hardware Failure	Compensatory measures in place @ 0818. Repaired, tested and back in service @ 09-16-94/1129.
03-94/082	09-14-94/1446	09-14-94/1445	CK # 1070 lost off site.	Human Error	CK # 1070 deleted from computer @ 1446. Access history report showed no unauthorized activity.
03-94/083	09-16-94/0016	09-15-94/2355	Door to vital area left unsecured.	Human Error	Security Officer posted @ 2358. Area searched with negative results.
03-94/084	09-18-94/1624	09-18-94/1524	PZ-26 M/W in constant intrusion alarm due to rain.	Hardware Failure	Security Officer posted @ 1524. Rain subsided, alarm cleared, and back in service @ 1613.
03-94/085	09-19-94/0245	09-19-94/0137	CK # 582 lost on site.	Human Error	CK # 582 deleted from computer @ 0138. Access history report showed no unauthorized activity.
03-94/086	09-19-94/0714	09-19-94/0714	CK # 529 Lost off site.	Human Error	CK # 529 Deleted from computer @ 0714. Access history showed no unauthorized activity.
03-94/087	09-19-94/1232	09-19-94/1232	CK # 1008 Lost on site.	Human Error	CK # 1008 found by Security Officer @ 1232. Checked for signs of tampering with negative results.
03-94/088	09-19-94/1634	09-19-94/1630	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1637. Rain subsided, M/W reset, tested and back in service @ 1803.
4/089	09-19-94/1637	09-19-94/1632	PZ-26 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1637. Rain stopped, M/W reset, tested and back in service @ 1902.
03-94/090	09-20-94/1419	09-20-94/1414	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1419. Area searched with negative results.
03-94/091	09-20-94/1423	09-20-94/1423	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1423. Rain subsided, M/W reset, tested and back in service @ 1806.
03-94/092	09-20-94/1423	09-20-94/1423	PZ-26 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1423. Rain subsided, M/W reset, tested and back in service @ 1851.
03-94/093	09-20-94/2055	09-20-94/2040	Keys found in vehicle by Security.	Human Error	Security Officer removed keys @ 2040, disabling vehicle.
03-94/094	09-22-94/1608	09-22-94/1309	Keys found in vehicle by Security.	Human Error	Security Officer removed keys @ 1309, disabling vehicle.
03-94/095	09-23-94/1336	09-23-94/1336	CK # 3276 lost on site.	Human Error	CK # 3276 found by S/O @ 1336. Checked for tampering with negative results. Access history report showed no unauthorized activity.
03-94/096	09-23-94/1918	09-23-94/1918	PZ-40 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1919. Rain subsided, M/W reset, tested and back in service @ 2115.

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
03-94/097	09-23-94/1932	09-23-94/1932	PZ-26 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 1933. Rain subsided. M/W reset, tested and back in service @ 2216.
03-94/098	09-23-94/2122	09-23-94/2122	PZ-04 washout under perimeter fence.	Hardware Failure	Security Officer posted @ 2122. Washout repaired, compensatory measures secured on 09-24-94 @ 1212 hrs.
03-94/099	09-26-94/0935	09-26-94/0650	CK # 391 Lost off site.	Human Error	CK # 391 turned in to security @ 0650. Access history report showed no unauthorized activity. CK checked for signs of tampering, with negative results, re-assigned to individual suffering loss @ 0720 hrs.
03-94/100	09-27-94/1450	09-27-94/1315	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1320. Area searched with negative results.
03-94/101	09-29-94/0719	09-29-94/0713	PZ-26 M/W stuck in intrusion due to rain.	Hardware Failure	Security Officer posted @ 0719. Rain subsided, M/W reset, tested and back in service @ 0939.
4/102	09-29-94/0845	09-29-94/0828	Door to vital area left unsecured.	Human Error	Security Officer posted @ 0833. Area searched with negative results.
03-94/103	09-30-94/2358	09-30-94/2252	Multiple Imux Failure	Hardware Failure	Compensatory measures in place @ 2300. System operational 10-01-94/0122. All required checks made and compensatory measures secured 10-01-94/0210.

Human Error = 41  
Hardware Failure = 62