



April 17, 1995

L-95-121
10 CFR 73.71

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: St. Lucie Units 1 and 2
Docket Nos: 50-335 and 50-389
Safeguards Event Log Entries
First Quarter 1995

Pursuant to 10 CFR 73.71(c)(2), Florida Power and Light Company is submitting a copy of St. Lucie Plant Safeguards Event Log Entries for the period January 1, 1995 to March 31, 1995. Based on changes to 10 CFR 73.71 effective on April 13, 1995, this is the last quarterly report.

The enclosed material does not contain safeguards information as defined by 10 CFR 73.21.

Very truly yours,

C. A. Buehler for

D. A. Sager
Vice President
St. Lucie Plant

DAS/GRM

Enclosure

cc: Stewart D. Ebnetter, Regional Administrator, USNRC Region II
Senior Resident Inspector, USNRC, St. Lucie Plant

Attachment

2-13-97

9504250238

13/pb

FLORIDA POWER & LIGHT

ST. LUCIE PLANT

QUARTERLY EVENT LOG

FIRST QUARTER 1995

January 1, 1995 through March 31, 1995

The Plant Disciplinary Policy for individuals who cause unsecured doors was modified on February 2, 1993 to increase the severity levels of discipline for offenders.

This is the last Quarterly Log to be submitted to the NRC.
(Rule change effective April 13, 1995)

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
0 1 95/001	- 01-02-95/0315	01-02-95/0242	Card Key (CK) # 558 Lost off site.	Human Error	CK # 558 deleted from computer @ 0244. Access history report showed no unauthorized activity.
0 1 95/002	- 01-02-95/1830	01-02-95/1426	PZ-08 Microwave (M/W) inoperative.	Hardware Failure	Security Officer posted @ 1426. M/W repaired, tested and back in service @ 01-03-95/1015.
0 1 95/003	- 01-02-95/1900	01-02-95/1830	PZ-36 M/W inoperative.	Hardware Failure	Security Officer posted @ 1830. M/W repaired, tested and back in service @ 01-03-95/1015.
0 1 95/004	- 01-03-95/0400	01-03-95/0224	Door to vital area left unsecured.	Human Error	Security Officer posted @ 0228. Area searched with negative results.
0 1 95/005	- 01-03-95/0700	01-03-95/0659	CK # 3017 Lost off site.	Human Error	CK # 3017 deleted from computer @ 0659. Access history report showed no unauthorized activity.
0 1 95/006	- 01-03-95/1325	01-03-95/1121	Vital door locking mechanism inoperative.	Hardware Failure	Security Officer posted @ 1121. Area searched with negative results. Door tested and back in service @ 1127.
0 1 95/007	- 01-04-95/0800	01-03-95/1128	Access Turnstile malfunction.	Hardware Failure	Malfunction in Turnstile caused turnstile to allow double access @ 1128. Malfunction could not be duplicated and tested operational @ 1130. On 01-04-95/0830 E/M was able to duplicate this problem. Turnstile was taken out of service and padlocked until repaired. Repaired, tested and back in service @ 01-06-94/1958.
0 1 95/008	- 01-05-95/2350	01-05-95/2320	CK # 1064 lost off site.	Human Error	CK # 1064 turned into security @ 2320. Access history report showed no unauthorized activity. CK checked for signs of tampering with negative results.
0 1 95/009	- 01-09-95/0545	01-09-95/0516	Single IMUX Failure.	Hardware Failure	Compensatory measures in place @ 0523. IMUX operational @ 0526. All tests completed and compensatory measures secured @ 0537.
0 1 95/010	- 01-09-95/1015	01-09-95/0826	Single IMUX Failure.	Hardware Failure	Compensatory measures in place @ 0832. IMUX operational @ 0941. All tests completed and compensatory measures secured @ 1012.
0 1 95/011	- 01-09-95/2250	01-09-95/1800	Vital key taken off site.	Human Error	Key was located, was taken home in error by a security officer. Key was returned to site by the Security Officer at 1845 hrs.
0 1 95/012	- 01-09-95/2300	01-09-95/1824	Access Turnstile malfunction.	Hardware Failure	Turnstile taken out of service, and padlocked until repaired. Repaired, tested and back in service @ 01-13-95/1710.
0 1 95/013	- 01-10-95/2200	01-10-95/2144	PZ-26 microwave in constant alarm.	Hardware Failure	S/O posted @ 2144 Hrs. M/W repaired, tested and back in service @ 01-11-95/0926.
0 1 95/014	- 01-11-95/0030	01-10-95/2357	CK # 0317 lost off site.	Human Error	CK # 0317 deleted from computer @ 2357. Access history report showed no unauthorized activity.
0 1 95/015	- 01-11-95/1620	01-11-95/1528	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1532. Area searched with negative results.
0 1 95/016	- 01-14-95/0200	01-13-95/1933	Single IMUX Failure.	Hardware Failure	Compensatory Measures in place @ 1940. IMUX operational @ 2233. All tests completed and compensatory measures secured @ 2258.
0 1 95/017	- 01-14-95/0930	01-14-95/0830	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	S/O posted @ 0830. Rain subsided, M/W reset, tested and back in service @ 0902. <u>Alarms Regenerated</u> 01-14-95/1432
0 1 95/018	- 01-14-95/1700	01-14-95/1616	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	S/O posted @ 1616. Rain subsided, M/W reset, tested and back in service @ 1941. <u>S/O in Place</u> 01-14-95/1432 <u>Back in service</u> 01-14-95/1547

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
0 1 95/019	- 01-15-95/0400	01-15-95/0320	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	S/O posted @ 0320. Rain subsided, M/W reset, tested and back in service @ 0453.
0 1 95/020	- 01-16-95/2130	01-16-95/1943	PZ-26 M/W in constant alarm.	Hardware Failure	Security Officer posted @ 1943. M/W repaired, tested and back in service @ 1-17-95/1146.
0 1 95/021	- 01-17-95/1705	01-17-95/1647	CK # 2752 Lost on site.	Human Error	CK # 2752 deleted from computer @ 1647. Access history report showed no unauthorized activity. CK found, checked for signs of tampering, with negative results, and reassigned to individual suffering the loss.
0 1 95/022	- 01-18-95/0220	01-17-95/1931	PZ-26 M/W in constant alarm.	Hardware Failure	Security Officer posted @ 1931. M/W repaired, tested and back in service @ 01-18-95/0917.
0 1 95/023	- 01-18-95/0700	01-18-95/0651	CK # 0157 lost off site.	Human Error	CK # 0157 deleted from computer @ 0653. Access history report showed no unauthorized activity.
0 1 95/024	- 01-20-95/2300	01-20-95/1728	PZ-26 M/W in constant alarm.	Hardware Failure	Security Officer posted @ 1728. M/W repaired, tested and back in service @ 01-23-95/1030.
0 1 95/025	- 01-25-95/1600	01-25-95/1332	Multiple IMUX failure.	Hardware Failure	Compensatory measures in place @ 1340. IMUX 10 & 12 operational @ 1358. All tests completed and compensatory measures secured @ 1433.
0 1 95/026	- 01-26-95/1735	01-26-95/1609	Smart Door Module (SDM) inoperative.	Hardware Failure	Security Officer posted @ 1615. SDM recovered, tested and back in service @ 1644.
0 1 95/027	- 01-27-95/1530	01-27-95/1324	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1327. Area searched with negative results.
0 1 95/028	- 01-27-95/1650	01-27-95/1624	CK # 0472 lost off site.	Human Error	CK # 0472 deleted from computer @ 1625. Access history report showed no unauthorized activity.
0 1 95/029	- 01-31-95/0300	01-31-95/0149	Vital door locking mechanism inoperative.	Hardware Failure	Security Officer posted @ 0150. Area searched with negative results. Door repaired, tested and back in service @ 0819.
0 1 95/030	- 01-31-95/1345	01-31-95/1024	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1030. Area searched with negative results.
0 1 95/031	- 02-01-95/1630	02-01-95/1253	PZ-26 M/W in constant alarm.	Hardware Failure	Security Officer posted @ 1253. M/W repaired, tested and back in service @ 1433. <u>Alarms Regenerated</u> <u>S/O in Place</u> <u>Back in service</u> 02-01-95/1523 02-01-95/1523 02-02-95/1438
0 1 95/032	- 02-02-95/1418	02-02-95/0718	CK # 2528 Lost off site.	Human Error	CK # 2528 deleted from computer @ 0719. Access history report showed no unauthorized activity.
0 1 95/033	- 02-04-95/1700	02-04-95/1209	PZ-26 M/W in constant alarm due to wind.	Hardware Failure	Security Officer posted @ 1209. Wind subsided, M/W reset, tested and back in service @ 2326.
0 1 95/034	- 02-07-95/0526	02-07-95/0526	Turnstile 203 SDM turned off due to multiple system messages.	Hardware Failure	Turnstile padlocked @ 0526. Turnstile repaired by I&C, tested and back in service @ 0939. <u>Turnstile padlocked</u> <u>Repaired, back in service</u> 02-07-95/1002 02-07-95/1054 02-07-95/1430 02-08-95/1041
0 1 95/035	- 02-07-95/1350	02-07-95/1300	CK # 1030 lost on site.	Human Error	CK # 1030 deleted from computer @ 1300. Access history report showed no unauthorized activity.

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
0 1 95/036	02-07-95/2100	02-07-95/2100	PZ- 26 M/W in constant alarm.	Hardware Failure	Security Officer posted @ 2100. M/W repaired, tested and back in service @ 02-08-95/1502.
0 1 95/037	02-07-95/2339	02-07-95/2337	CK # 878 Lost off site.	Human Error	CK # 878 deleted from computer @ 2339. Access history report showed no unauthorized activity.
0 1 95/048	02-08-95/0815	02-08-95/0616	CK # 329 Lost off site.	Human Error	CK # 329 turned into security @ 0616. Access history report showed no unauthorized activity. CK checked for signs of tampering with negative results.
0 1 95/039	02-09-95/1615	02-08-95/1340	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1344. Area searched with negative results.
0 1 95/040	02-10-95/1555	02-05-95/1549	CK # 4821 lost on site.	Human Error	CK # 4821 deleted from computer @ 1550. Access history report showed no unauthorized activity.
0 1 95/041	02-10-95/1625	02-10-95/1614	CK # 1809 lost off site.	Human Error	CK # 1809 deleted from computer @ 1615. Access history report showed no unauthorized activity.
0 1 95/042	02-13-95/2200	02-13-95/1851	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1851. Rain subsided, M/W reset, back in service @ 1928. <u>Alarms Regenerated</u> <u>S/O in Place</u> <u>Back in service</u> 02-13-95/2122 02-13-95/2122 02-14-95/0051
0 1 95/043	02-13-95/2205	02-13-95/1851	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1851. Rain subsided, M/W reset, back in service @ 1928. <u>Alarms Regenerated</u> <u>S/O in Place</u> <u>Back in service</u> 02-13-95/2121 02-13-95/2121 02-14-95/0051
0 1 95/044	02-14-95/2100	02-14-95/1758	CK # 2769 lost off site.	Human Error	CK # 2769 deleted from computer @ 1800. Access history report showed no unauthorized activity.
0 1 95/045	02-25-95/0700	02-24-95/1013	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1013. Area searched with negative results.
0 1 95/046	02-24-95/1830	02-24-95/1800	Access Turnstile malfunction.	Hardware Failure	Malfunction in turnstile caused turnstile to free-wheel. Turnstile taken out of service and padlocked at 1800. Repaired, tested and back in service @ 02-28-95/2130.
0 1 95/047	02-25-95/1000	02-25-95/0925	Door to vital area left unsecured.	Human Error	Security Officer posted @ 0925. Area searched with negative results.
0 1 95/048	02-25-95/1800	02-25-95/1712	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1713. Rain subsided, M/W reset, back in service @ 1736. <u>Alarms Regenerated</u> <u>S/O in Place</u> <u>Back in service</u> 02-25-95/2245 02-25-95/2247 02-26-95/0045
0 1 95/049	02-25-95/1800	02-25-95/1713	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1714. Rain subsided, M/W reset, back in service @ 1736. <u>Alarms Regenerated</u> <u>S/O in Place</u> <u>Back in service</u> 02-25-95/2231 02-25-95/2234 02-26-95/0045
0 1 95/050	02-28-95/0610	02-28-95/0434	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 0436. Rain subsided, M/W reset, tested and back in service @ 02-28-95/0545.
0 1 95/051	02-28-95/0610	02-28-95/0436	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 0438. Rain subsided, M/W reset, back in service @ 02-28-95/0545.
0 1 95/052	02-28-95/1340	02-28-95/0739	Vital Door Alarm Point inoperative.	Hardware Failure	Alarm Point found to be inoperative during operability testing. Security Officer posted @ 0739. Repaired, tested and back in service @ 0839.

LOG NO. LOG ENTRY
DATE/TIME

L-95-121
10 CFR 73.71

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: St. Lucie Units 1 and 2
Docket Nos. 50-335 and 50-389
Safeguards Event Log Entries
First Quarter 1995

Pursuant to 10 CFR 73.71(c)(2), Florida Power and Light Company is submitting a copy of St. Lucie Plant Safeguards Event Log Entries for the period January 1, 1995 to March 31, 1995.

The enclosed material does not contain safeguards information as defined by 10 CFR 73.21.

Very truly yours,

D. A. Sager
Vice President
St. Lucie Plant

DAS/GRM

Enclosure

cc: Stewart D. Ebnetter, Regional Administrator, USNRC Region II
Senior Resident Inspector, USNRC, St. Lucie Plant

Attachment

4/9

FLORIDA POWER & LIGHT

ST. LUCIE PLANT

QUARTERLY EVENT LOG

FIRST QUARTER 1995

January 1, 1995 through March 31, 1995

The Plant Disciplinary Policy for individuals who cause unsecured doors was modified on February 2, 1993 to increase the severity levels of discipline for offenders.

This is the last Quarterly Log to be submitted to the NRC.
(Rule change effective April 13, 1995)

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
0 1 95/001	- 01-02-95/0315	01-02-95/0242	Card Key (CK) # 558 Lost off site.	Human Error	CK # 558 deleted from computer @ 0244. Access history report showed no unauthorized activity.
0 1 95/002	- 01-02-95/1830	01-02-95/1426	PZ-08 Microwave (M/W) inoperative.	Hardware Failure	Security Officer posted @ 1426. M/W repaired, tested and back in service @ 01-03-95/1015.
0 1 95/003	- 01-02-95/1900	01-02-95/1830	PZ-36 M/W inoperative.	Hardware Failure	Security Officer posted @ 1830. M/W repaired, tested and back in service @ 01-03-95/1015.
0 1 95/004	- 01-03-95/0400	01-03-95/0224	Door to vital area left unsecured.	Human Error	Security Officer posted @ 0228. Area searched with negative results.
0 1 95/005	- 01-03-95/0700	01-03-95/0659	CK # 3017 Lost off site.	Human Error	CK # 3017 deleted from computer @ 0659. Access history report showed no unauthorized activity.
0 1 95/006	- 01-03-95/1325	01-03-95/1121	Vital door locking mechanism inoperative.	Hardware Failure	Security Officer posted @ 1121. Area searched with negative results. Door tested and back in service @ 1127.
0 1 95/007	- 01-04-95/0800	01-03-95/1128	Access Turnstile malfunction.	Hardware Failure	Malfunction in Turnstile caused turnstile to allow double access @ 1128. Malfunction could not be duplicated and tested operational @ 1130. On 01-04-95/0830 E/M was able to duplicate this problem. Turnstile was taken out of service and padlocked until repaired. Repaired, tested and back in service @ 01-06-94/1958.
0 1 95/008	- 01-05-95/2350	01-05-95/2320	CK # 1064 lost off site.	Human Error	CK # 1064 turned into security @ 2320. Access history report showed no unauthorized activity. CK checked for signs of tampering with negative results.
0 1 95/009	- 01-09-95/0545	01-09-95/0516	Single IMUX Failure.	Hardware Failure	Compensatory measures in place @ 0523. IMUX operational @ 0526. All tests completed and compensatory measures secured @ 0537.
0 1 95/010	- 01-09-95/1015	01-09-95/0826	Single IMUX Failure.	Hardware Failure	Compensatory measures in place @ 0832. IMUX operational @ 0941. All tests completed and compensatory measures secured @ 1012.
0 1 95/011	- 01-09-95/2250	01-09-95/1800	Vital key taken off site.	Human Error	Key was located, was taken home in error by a security officer. Key was returned to site by the Security Officer at 1845 hrs.
0 1 95/012	- 01-09-95/2300	01-09-95/1824	Access Turnstile malfunction.	Hardware Failure	Turnstile taken out of service, and padlocked until repaired. Repaired, tested and back in service @ 01-13-95/1710.
0 1 95/013	- 01-10-95/2200	01-10-95/2144	PZ-26 microwave in constant alarm.	Hardware Failure	S/O posted @ 2144 Hrs. M/W repaired, tested and back in service @ 01-11-95/0926.
0 1 95/014	- 01-11-95/0030	01-10-95/2357	CK # 0317 lost off site.	Human Error	CK # 0317 deleted from computer @ 2357. Access history report showed no unauthorized activity.
0 1 95/015	- 01-11-95/1620	01-11-95/1528	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1532. Area searched with negative results.
0 1 95/016	- 01-14-95/0200	01-13-95/1933	Single IMUX Failure.	Hardware Failure	Compensatory Measures in place @ 1940. IMUX operational @ 2233. All tests completed and compensatory measures secured @ 2258.
0 1 95/017	- 01-14-95/0930	01-14-95/0830	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	S/O posted @ 0830. Rain subsided, M/W reset, tested and back in service @ 0902. <u>Alarms Regenerated</u> 01-14-95/1432
0 1 95/018	- 01-14-95/1700	01-14-95/1616	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	S/O posted @ 1616. Rain subsided, M/W reset, tested and back in service @ 1941. <u>S/O in Place</u> 01-14-95/1432 <u>Back in service</u> 01-14-95/1547

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
0 1 95/019	- 01-15-95/0400	01-15-95/0320	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	S/O posted @ 0320. Rain subsided, M/W reset, tested and back in service @ 0453.
0 1 95/020	- 01-16-95/2130	01-16-95/1943	PZ-26 M/W in constant alarm.	Hardware Failure	Security Officer posted @ 1943. M/W repaired, tested and back in service @ 1-17-95/1146.
0 1 95/021	- 01-17-95/1705	01-17-95/1647	CK # 2752 Lost on site.	Human Error	CK # 2752 deleted from computer @ 1647. Access history report showed no unauthorized activity. CK found, checked for signs of tampering, with negative results, and reassigned to individual suffering the loss.
0 1 95/022	- 01-18-95/0220	01-17-95/1931	PZ-26 M/W in constant alarm.	Hardware Failure	Security Officer posted @ 1931. M/W repaired, tested and back in service @ 01-18-95/0917.
0 1 95/023	- 01-18-95/0700	01-18-95/0651	CK # 0157 lost off site.	Human Error	CK # 0157 deleted from computer @ 0653. Access history report showed no unauthorized activity.
0 1 95/024	- 01-20-95/2300	01-20-95/1728	PZ-26 M/W in constant alarm.	Hardware Failure	Security Officer posted @ 1728. M/W repaired, tested and back in service @ 01-23-95/1030.
0 1 95/025	- 01-25-95/1600	01-25-95/1332	Multiple IMUX failure.	Hardware Failure	Compensatory measures in place @ 1340. IMUX 10 & 12 operational @ 1358. All tests completed and compensatory measures secured @ 1433.
0 1 95/026	- 01-26-95/1735	01-26-95/1609	Smart Door Module (SDM) inoperative.	Hardware Failure	Security Officer posted @ 1615. SDM recovered, tested and back in service @ 1644.
0 1 95/027	- 01-27-95/1530	01-27-95/1324	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1327. Area searched with negative results.
0 1 95/028	- 01-27-95/1650	01-27-95/1624	CK # 0472 lost off site.	Human Error	CK # 0472 deleted from computer @ 1625. Access history report showed no unauthorized activity.
0 1 95/029	- 01-31-95/0300	01-31-95/0149	Vital door locking mechanism inoperative.	Hardware Failure	Security Officer posted @ 0150. Area searched with negative results. Door repaired, tested and back in service @ 0819.
0 1 95/030	- 01-31-95/1345	01-31-95/1024	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1030. Area searched with negative results.
0 1 95/031	- 02-01-95/1630	02-01-95/1253	PZ-26 M/W in constant alarm.	Hardware Failure	Security Officer posted @ 1253. M/W repaired, tested and back in service @ 1433. <u>Alarms Regenerated</u> <u>S/O in Place</u> <u>Back in service</u> 02-01-95/1523 02-01-95/1523 02-02-95/1438
0 1 95/032	- 02-02-95/1418	02-02-95/0718	CK # 2523 Lost off site.	Human Error	CK # 2528 deleted from computer @ 0719. Access history report showed no unauthorized activity.
0 1 95/033	- 02-04-95/1700	02-04-95/1209	PZ-26 M/W in constant alarm due to wind.	Hardware Failure	Security Officer posted @ 1209. Wind subsided, M/W reset, tested and back in service @ 2326.
0 1 95/034	- 02-07-95/0526	02-07-95/0526	Turnstile 203 SDM turned off due to multiple system messages.	Hardware Failure	Turnstile padlocked @ 0526. Turnstile repaired by I&C, tested and back in service @ 0939. <u>Turnstile padlocked</u> <u>Repaired, back in service</u> 02-07-95/1002 02-07-95/1054 02-07-95/1430 02-08-95/1041
0 1 95/035	- 02-07-95/1350	02-07-95/1300	CK # 1030 lost on site.	Human Error	CK # 1030 deleted from computer @ 1300. Access history report showed no unauthorized activity.

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
0 1 95/036	02-07-95/2100	02-07-95/2100	PZ- 26 M/W in constant alarm.	Hardware Failure	Security Officer posted @ 2100. M/W repaired, tested and back in service @ 02-08-95/1502.
0 1 95/037	02-07-95/2339	02-07-95/2337	CK # 878 Lost off site.	Human Error	CK # 878 deleted from computer @ 2339. Access history report showed no unauthorized activity.
0 1 95/048	02-08-95/0815	02-08-95/0616	CK # 329 Lost off site.	Human Error	CK # 329 turned into security @ 0616. Access history report showed no unauthorized activity. CK checked for signs of tampering with negative results.
0 1 95/039	02-09-95/1615	02-08-95/1340	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1344. Area searched with negative results.
0 1 95/040	02-10-95/1555	02-05-95/1549	CK # 4821 lost on site.	Human Error	CK # 4821 deleted from computer @ 1550. Access history report showed no unauthorized activity.
0 1 95/041	02-10-95/1625	02-10-95/1614	CK # 1809 lost off site.	Human Error	CK # 1809 deleted from computer @ 1615. Access history report showed no unauthorized activity.
0 1 95/042	02-13-95/2200	02-13-95/1851	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1851. Rain subsided, M/W reset, back in service @ 1928. <u>Alarms Regenerated</u> <u>S/O in Place</u> <u>Back in service</u> 02-13-95/2122 02-13-95/2122 02-14-95/0051
0 1 95/043	02-13-95/2205	02-13-95/1851	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1851. Rain subsided, M/W reset, back in service @ 1928. <u>Alarms Regenerated</u> <u>S/O in Place</u> <u>Back in service</u> 02-13-95/2121 02-13-95/2121 02-14-95/0051
0 1 95/044	02-14-95/2100	02-14-95/1758	CK # 2769 lost off site.	Human Error	CK # 2769 deleted from computer @ 1800. Access history report showed no unauthorized activity.
0 1 95/045	02-25-95/0700	02-24-95/1013	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1013. Area searched with negative results.
0 1 95/046	02-24-95/1830	02-24-95/1800	Access Turnstile malfunction.	Hardware Failure	Malfunction in turnstile caused turnstile to free-wheel. Turnstile taken out of service and padlocked at 1800. Repaired, tested and back in service @ 02-28-95/2130.
0 1 95/047	02-25-95/1000	02-25-95/0925	Door to vital area left unsecured.	Human Error	Security Officer posted @ 0925. Area searched with negative results.
0 1 95/048	02-25-95/1800	02-25-95/1712	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1713. Rain subsided, M/W reset, back in service @ 1736. <u>Alarms Regenerated</u> <u>S/O in Place</u> <u>Back in service</u> 02-25-95/2245 02-25-95/2247 02-26-95/0045
0 1 95/049	02-25-95/1800	02-25-95/1713	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1714. Rain subsided, M/W reset, back in service @ 1736. <u>Alarms Regenerated</u> <u>S/O in Place</u> <u>Back in service</u> 02-25-95/2231 02-25-95/2234 02-26-95/0045
0 1 95/050	02-28-95/0610	02-28-95/0434	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 0436. Rain subsided, M/W reset, tested and back in service @ 02-28-95/0545.
0 1 95/051	02-28-95/0610	02-28-95/0436	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 0438. Rain subsided, M/W reset, back in service @ 02-28-95/0545.
0 1 95/052	02-28-95/1340	02-28-95/0739	Vital Door Alarm Point inoperative.	Hardware Failure	Alarm Point found to be inoperative during operability testing. Security Officer posted @ 0739. Repaired, tested and back in service @ 0839.

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
0 1 95/053	- 02-28-95/1400	02-28-95/1115	CK # 2216 lost on site.	Human Error	CK # 2216 deleted from computer @ 1116. Access history report showed no unauthorized activity.
0 1 95/054	- 03-01-95/1200	03-01-95/0944	Access Turnstile malfunction.	Hardware Failure	Malfunction in turnstile caused turnstile to free-wheel. Turnstile taken out of service and padlocked @ 0944. Repaired, tested and back in service @ 1755.
0 1 95/055	- 03-06-95/0200	03-06-95/0010	Door to vital area left unsecured.	Human Error	Security Officer posted @ 0011. Area searched with negative results.
0 1 95/056	- 03-08-95/1245	03-08-95/0911	Missing Training Aid.	Human Error	Non-Serviceable Beretta Pistol 92FS (Serial # BER117489Z) missing. Plant site searched with negative results. Pistol recovered on 03-12-95/1713.
0 1 95/057	- 03-08-95/1250	03-08-95/1226	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1228. Rain subsided, M/W reset, back in service @ 1251.
0 1 95/058	- 03-09-95/2330	03-09-95/2202	CK # 1064 lost on site.	Human Error	CK # 1064 deleted from computer @ 2204. Access history report showed no unauthorized activity.
0 1 95/059	- 03-10-95/1900	03-10-95/1715	ESS Failure.	Hardware Failure	Compensatory measures in place @ 1723. System operational @ 1801. All required checks made and compensatory measures secured @ 1859. RE: Free Pool Exhausted.
0 1 95/060	- 03-10-95/1050	03-10-95/2221	CK # 0209 lost off site.	Human Error	CK # 0209 deleted from computer @ 2223. Access history report showed no unauthorized activity.
0 1 95/061	- 03-13-95/1045	03-13-95/0957	PZ-26 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1000. Rain subsided, M/W reset, back in service @ 1032. <u>Alarms Regenerated</u> <u>S/O In Place</u> <u>Back in service</u> 03-13-95/1844 03-13-95/1848 03-13-95/1954
0 1 95/062	- 03-13-95/1050	03-13-95/0958	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1000. Rain subsided, M/W reset, back in service @ 1031. <u>Alarms Regenerated</u> <u>S/O In Place</u> <u>Back in service</u> 03-13-95/1843 03-13-95/1845 03-13-95/1954
0 1 95/063	- 03-13-95/1600	03-13-95/1345	CK # 121 lost on site.	Human Error	CK # 121 turned into security @ 1345. Access history report showed no unauthorized activity. CK checked for signs of tampering, with negative results, and reassigned to individual suffering the loss.
0 1 95/064	- 03-14-95/0225	03-13-95/1935	CK # 4760 lost off site.	Human Error	CK # 4760 deleted from computer @ 1937. Access history report showed no unauthorized activity.
0 1 95/065	- 03-14-95/1620	03-14-95/1603	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1605. Area searched with negative results.
0 1 95/066	- 03-16-95/0644	03-16-95/0644	Access turnstile malfunction.	Hardware Failure	Malfunction in turnstile caused turnstile to free-wheel. Turnstile taken out of service and padlocked @ 0644. Repaired, tested and back in service @ 03-17-95/0410.
0 1 95/067	- 03-16-95/1400	03-16-95/1115	CK # 1978 lost on site.	Human Error	CK # 1978 deleted from computer @ 1115. Access history report showed no unauthorized activity.
0 1 95/068	- 03-17-95/1530	03-17-95/1230	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1230. Rain subsided, M/W reset, back in service @ 1426.
0 1 95/069	- 03-18-95/1315	03-18-95/1223	Door to vital area left unsecured.	Human Error	Security Officer posted @ 1226. Area searched with negative results.

LOG NO.	LOG ENTRY DATE/TIME	EVENT DATE/TIME	EVENT	REASON AND/OR CODE	RESPONSE
0 1 95/070	- 03-18-95/1530	03-18-95/1433	PZ-40 M/W in constant alarm due to rain.	Hardware Failure	Security Officer posted @ 1433. Rain subsided, M/W reset, back in service @ 1505.
0 1 95/071	- 03-22-95/1400	03-22-95/0748	CK # 762 lost off site.	Human Error	CK # 762 deleted from computer @ 0748. Access history report showed no unauthorized activity.
0 1 95/072	- 03-23-95/1600	03-23-95/1356	CK # 439 lost on site.	Human Error	CK # 439 deleted from computer @ 1357. Access history report showed no unauthorized activity.
0 1 95/073	- 03-24-95/0230	03-24-95/0052	PZ-23 CCTV lost.	Hardware Failure	CCTV lost due to camera malfunction. Security Officer posted @ 0054. CCTV repaired, back in service @ 0937.
0 1 95/074	- 03-24-95/1000	03-24-95/0809	CK # 1271 lost on site.	Human Error	CK # 1271 deleted from computer @ 0810. Access history report showed no unauthorized activity.
0 1 95/075	- 03-27-95/1600	03-27-95/0940	CK # 712 lost off site.	Human Error	CK # 712 deleted from computer @ 0941. Access history report showed no unauthorized activity.
0 1 95/076	- 03-27-95/1700	03-27-95/1335	Multiple IMUX failure.	Human Error	Compensatory measures in place @ 1342. IMUX's operational @ 1439. All tests completed and compensatory measures secured @ 1524. RE: Electrician accidentally turned off circuit breaker.
0 1 95/077	- 03-28-95/1130	03-28-95/0720	CK # 340 lost off site.	Human Error	CK # 340 deleted from computer @ 0721. Access history report showed no unauthorized activity.
0 1 95/078	- 03-28-95/1410	03-28-95/1231	CK # 2835 lost on site.	Human Error	CK # 2835 turned into security @ 1231. Access history report showed no unauthorized activity. CK checked for signs of tampering, with negative results, and reassigned to individual suffering the loss.
0 1 95/079	- 03-29-95/0709	03-29-95/0610	Vital door locking mechanism inoperative.	Hardware Failure	Security Officer posted @ 0615. Area searched with negative results. Door operational, tested and back in service @ 0620.
0 1 95/080	- 03-29-95/1630	03-29-95/1149	Contractor access suspended due to criminal history.	Human Error	Access suspended pending investigation.
0 1 95/081	- 03-30-95/0210	03-30-95/0142	PZ-23 CCTV lost.	Hardware Failure	CCTV lost due to camera malfunction. Security Officer posted @ 0144. CCTV operational, back in service @ 03-30-95/0610.
0 1 95/082	- 03-30-95/1430	03-30-95/1308	Single IMUX Failure.	Hardware Failure	Compensatory measures in place @ 1314. IMUX operational @ 1320. All tests completed and compensatory measures secured @ 1350.

Human Error = 40
Hardware Failure = 42