

# SAFENIGHT TECHNOLOGY INC.

*"the safer smoke detector network"*

2121 Electric Road SW  
Roanoke, Virginia 24018  
(703) 989-5738

February 8, 1996

Ms. Michelle Burgess, Mechanical Engineer  
United States Nuclear Regulatory Commission  
#2 Wide Flint North  
11555 Rockville Pike T-8f5  
Rockville, MD 20852

Re: Response to February 8th Deficiency call


Dear Michelle:

In response to your call:

This letter is to amend our January 31st response. In error, we failed to update our point-of-purchase packaging to include our USNRC number. This letter is to confirm and state that our point-of-purchase packaging will include (our) "USNRC License #XXXXXXXXXXXX" in addition to other USNRC information stated on the packaging sample.

Thank you and I look forward to your next correspondence.

Sincerely,



Scott N. Markwell  
President

SNM/ct

# SAFENIGHT TECHNOLOGY INC.

---

*"the safer smoke detector network"*

2121 Electric Road SW  
Roanoke, Virginia 24018  
(703) 989-5738

## F A X   T R A N S M I T T A L   S H E E T

To: Mr. Michelle Burgess, Mechanical Engineer

Company: USNRC

Regarding: Response

Number of pages (including this sheet) 2

From: Scott N. Markwell

**SAFENIGHT TECHNOLOGY INC.**

*"the safer smoke detector network"*

2121 Electric Road SW  
Roanoke, Virginia 24018



Ms. Michelle Burgess, Mechanical Engineer  
United States Nuclear Regulatory Commission  
Mailstop T-8f5  
Washington, DC 20555





UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D.C. 20555-0001

Mr. Scott N. Markwell  
SafeNight Technology Inc.  
2121 Electric Road SW  
Roanoke, VA 24018

Dear Mr. Markwell:

This letter is in response to your letter dated January 31, 1996, providing additional information regarding your Model SN-100 Series and SN-500 Series smoke detectors. We are in the process of re-evaluating your request. However, in order to continue our evaluation, the following information is necessary:

1. In your resubmission dated December 29, 1995, you state that the point-of-sale label will contain the "U.S. NRC License No. XXX". The samples of the point-of-sale package provided in your January 31, 1996, letter does not show the license number on the packaging. Please clarify this discrepancy.
2. The auditing procedures provided for the testing contractor:  
Q# 23 in the 1/31/96 letter - Q# 23 on page B19 of the new QA audit procedures. From what we have talked about, that belongs in the manufacturer's part not in the testers part. please explain why it is contained here.

*see above*

*he will send for 2/7*

*phone call 2/8/96 left msg for Scott Markwell on 2/7/96 540 989 5738*