


VERMONT YANKEE NUCLEAR POWER CORPORATION



P.O. Box 157, Governor Hunt Road
Vernon, Vermont 05354-0157
(802) 257-7711

REPLY TO
ENGINEERING OFFICE
580 MAIN STREET
BOLTON, MA 01740

January 27, 1996
BVY-97-13

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

References: a) License No. DPR-28 (Docket No. 50-271)

Subject: Vermont Yankee 1996 Summary Reports for Inservice Inspection and Repairs and Replacements.

In accordance with Article IWA-6000 of Section XI of the ASME Boiler and Pressure Vessel Code, we hereby submit the Vermont Yankee Owner's Report for Inservice Inspections (Form NIS-1) and the Owner's Report for Repairs or Replacements (Form NIS-2). These reports describe the inservice examinations and repairs and replacements performed during the period from May 3, 1995 through November 2, 1996 (including RFO 19). Vermont Yankee's third ten-year interval began September 1, 1993.

We trust that the information provided is adequate; however should you have any questions or require additional information, please do not hesitate to contact us.

Sincerely,
Vermont Yankee Nuclear Power Corporation

E. V. Lindamood
Director of Engineering

030010

cc: USNRC Regional Administrator
USNRC Resident Inspector - VYNPS
USNRC Project Manager - VYNPS
Inspection Agency - Arkwright

9702030053 970127
PDR ADOCK 05000271
G PDR

1047
1/1