

DMB COPY

AUG 13 1985

Jewish Hospital
ATTN: Paul A. Feller, Ph.D.
Director, Physics Services
and Radiation Safety
Officer
3200 Burnet Avenue
Cincinnati, Ohio 45229

License No. 34-00855-07

30-14033

Gentlemen:


This refers to the special safety inspection conducted by S. R. Lasuk of this office on July 15, 1985, of activities authorized by NRC Byproduct Materials License No. 34-00855-07, and to the discussion of our findings with you at the conclusion of the inspection. This also acknowledges receipt of your letter dated July 19, 1985, which is a followup to your May 3, 1985 incident report.

The inspection was conducted because of a reported unintentional exposure of a brachytherapy patient to radiation and was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. One violation of NRC requirements was identified during the inspection of your routine activities, as specified in the enclosed Appendix. You will note that no response is required regarding this violation.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



W. L. Axelson, Chief
Nuclear Materials Safety
and Safeguards Branch

8508160344 850813
REG3 LIC30
34-00855-07 PDR

Enclosures:


1. Appendix, Notice of Violation
2. Inspection Report
No. 030-14033/85001(DRSS)

cc w/enclosures:
DMB/Document Control Desk (RIDS)

RIII

Lasuk/ld
08/05/85

RIII

Sreniawski
8/8

RIII

Axelson
8/12/85

IE07
11