



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV

611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76011

October 1, 1982

Docket File  
40-8752


Thomas Clary  
Star Route Box 15  
Miami, AZ 85539

Dear Mr. Clary:

This letter is in reference to NRC License SUA-1388 issued to Pinal Minerals and Mining, Ltd., of Globe, Arizona. For some months, individuals from our Uranium Recovery Licensing Branch and from the NRC Region IV office have been attempting to determine the current status of licensed activities, and to notify the licensee that on October 1, 1982, the license will expire and that steps must be taken to renew or retire the license. In addition, we are planning to conduct an inspection at the site during the week of October 12, 1982.

According to our information, you were managing the licensed activities for Pinal on our visit to the facility during August 1980. For this reason, we request that you: (1) inform us by telephone of the current status of licensed activities and (2) make arrangements to meet with our inspector during the week of October 12, 1982, for a site visit. At your earliest opportunity, please contact me or Mr. D. B. Spitzberg collect at (817) 860-8184 to discuss this matter further.

Sincerely,

  
Glen D. Brown, Chief  
Technical Programs Branch

✓ cc: Dan Gillen, WMUR

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

9609300080 821001  
PDR ADOCK 04008752  
C PDR