



UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

URANIUM RECOVERY FIELD OFFICE  
BOX 25325  
DENVER, COLORADO 80225

DATE: April 18, 1983

NOTE TO

DOCKET FILE: 40-8752

FROM: Daniel M. Gillen, Project Manager  
Licensing Branch 1, URFO

SUBJECT: REVIEW OF MAIL CONTROL NO. 00183

I have reviewed the subject document and have concluded the following:

- ☐ This document contains information that is not essential to the review and maintenance of this license and no further regulatory review or consideration is warranted.
- ☒ This document contains information that was previously submitted and reviewed and no further action is warranted.
- ☐ This document contains substantive information that is summarized below; however, no further regulatory action is warranted.
- ☐ This document contains substantive information that is summarized below and is essential to the review and maintenance of this license. Further regulatory review or consideration is necessary.

SUMMARY: The information in this inspection report was  
previously reviewed as part of an amendment of SUA-1388  
presently in progress.

DATE DUE TO DOCKET FILE: APR 30 1983