

SAFETY INSPECTION

1. LICENSEE <b>Reuter-Stokes, Inc.</b> <b>8499 Darrow Road</b> <b>Twinsburg, Ohio</b>		2. REGIONAL OFFICE <b>U.S. NUCLEAR REGULATORY COMMISSION</b> <b>REGION III</b> <b>799 ROOSEVELT ROAD</b> <b>GLEN ELLYN, ILLINOIS 60137</b>	
3. DOCKET NUMBER(S) <b>070-02872</b> <b>030-030-14408</b>	4. LICENSE NUMBER(S) <b>SNM-1826</b> <b>34-18156-01</b> <b>34-18233-01</b>	5. DATE OF INSPECTION <b>August 1 and 2, 1985</b>	

Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☐ 1. Within the scope of this inspection, no violations were observed.
- ☒ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. **We have no further questions on these actions at this time. Item J. outlined below is a repeat violation.**
- ☒ 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements. **(Items H and J).**  
**THIS IS A NOTICE OF VIOLATION** which is required to be posted in accordance with 10 CFR 19.11.
- ☐ A. \_\_\_\_\_ was not properly posted to indicate the presence of a \_\_\_\_\_ 10 CFR 20.203(b), (c), (d), (e) or 34.42.
- ☐ B. Containers located in \_\_\_\_\_ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).
- ☐ C. \_\_\_\_\_ of sealed sources were not performed at the proper frequencies. 10 CFR \_\_\_\_\_ License Condition Number \_\_\_\_\_.
- ☐ D. Records of \_\_\_\_\_ were not properly maintained. 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
- ☐ E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
- ☐ F. Reports or notifications of \_\_\_\_\_ were not made in accordance with 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
- ☒ H. **Formal Annual retraining of technicians not performed. Also, initial training provided to technicians not documented. This is contrary to referenced license applications dated May 26, 1978 and May 30, 1983. (Pertains to all three licenses)**
- ☒ J. **Weekly radiation surveys of radioactive material storage room not performed between May thru September 1984. This is contrary to referenced application dated January 9, 1978.**
- ☐ K. **(pertains to Lic No. 34-18233-01)**

I hereby state that within 30 days the actions described in this statement of corrective actions is made in accordance with the NRC.

8508190107 850802  
REG3 LIC30  
34-18156-01 PDR

actions identified in the items checked above. response will be submitted unless required by

SIGNATURE - LICENSEE

DATE

SIGNATURE - NRC INSPECTOR

DATE

IE07

0/1