

AUG 14 1985

Docket No. 50-346


Toledo Edison Company
ATTN: Mr. Joe Williams, Jr.
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

On July 1, 1985, you provided us with clarifying information regarding item 1 of our Confirmatory Action Letter issued on June 10, 1985. The purpose of this letter is to clarify the exact nature of steps that need to be taken before corrective actions are initiated for hardware problems which were identified.

With respect to the specific steps outlined in your letter, we understand that you will; a) provide to the NRC Resident Inspectors your plans to investigate each failure prior to the start of troubleshooting activities; b) upon completion of the investigation of any particular activity, submit your determination of the root cause of the malfunction and failure to the Office of NRR with a copy to Region III. You should also submit general corrective actions that you plan to take to address the root causes. Initiation of work on the corrective actions is not dependent upon NRC approval; and c) the Region III Resident Inspectors' office should be notified of the plans and schedules for carrying out the corrective action work prior to the work being performed.

Sincerely,



James G. Keppler
Regional Administrator

cc: L. Storz, Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert H. Quillin, Ohio
Department of Health

RIII
HP
Burgess/ls
08/13/85

RIII
HP
Jackiw

RIII
HP
Chrissotimos

RIII
HP
Morelius

RIII
HP
Berson
8/13

RIII
HP
Davis
8/13

RIII
HP
Keppler
8/13

8508190202 850814
PDR ADOCK 05000346
S PDR

IED01