

Q30 14251

DMB COPY

AUG 10 1985

Floro Miraldi, M.D.
3116 Fairmount Blvd.
Cleveland Heights, OH 44118

License No. 34-18843-01

Dr. Miraldi:

This refers to the routine safety inspection conducted by Mr. W. J. Slawinski of this office on July 29, 1985, of activities authorized by NRC Byproduct Material License No. 34-18843-01 and to the discussion of our findings with Mr. Vito Salvo at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.


In addition to the above areas, the inspector examined actions described in your letter dated November 30, 1981, regarding apparent items of noncompliance found during our October 13, 1981 inspection. We have no further questions regarding these matters.

Regarding License Condition No. 12, one of your authorized technologists may administer radiopharmaceuticals without you or Dr. Rejali's physical presence, with the following stipulation. A licensed physician with at least thirty hours of training in basic radiological handling techniques must be on-site at the time radiopharmaceuticals are administered.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. J. Sreniawski, Chief
Nuclear Materials Safety Section 2

8508200268 850816
REG3 LIC30
34-18843-01 PDR

cc: DMB/Document Control Desk (RIDS)

RIII

Slawinski/jp
08/14/85

RIII

Sreniawski

8/15

IE07

110