

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-369

UNIT NAME McGuire 1

DATE 7/15/85

COMPLETED BY J. A. Reavis

TELEPHONE 704-373-7567

PAGE 1 of 2

REPORT MONTH June 1985

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	License Event Report #	Systems Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
4	85-06-01	S	317.03	C	4		RC	FUELXX	End of Cycle 2 Refueling Outage
4A	85-06-14	F	24.00	A	4		RD	VALVEX	Extension due to repair of fuel transfer tube isolation valve.
4B	85-06-15	F	72.00	A	4		CB	HEATEX	Extension due to Eddy Current test problems on the steam generator.
4C	86-06-18	F	72.00	A	4		CA	VESSEL	Extension due to head area work delays.
4D	85-06-21	F	24.00	A	4		CB	HEATEX	Extension due to steam generator man-way tensioner modification.
4E	85-06-22	F	24.00	A	4		CB	VALVEX	Extension due to repair of binding pressurizer spray control valve.
4F	85-06-23	F	48.00	A	4		SF	ACCUMU	Extension due to repair of seat on accumulator containment isolation sample valve.
4G	85-06-25	F	24.00	F	4		XX	XXXXXX	Extension due to containment cleanliness

8508200604 850815
PDR ADOCK 05000369
R PDR

1

F Forced
S Scheduled

2

Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

3

Method:
1-Manual
2-Manual Scram
3-Automatic Scram
4-Other (Explain)

4

Exhibit G - Instructions
for Preparation of Data
Entry Sheets for Licensee
Event Report (LER)
File (NUREG-0161)

5

Exhibit I - Same Source