

NMSS:JEW
Control No. 460629

JUN 13 1985

Community Hospital
ATTN: Talton L. Francis
Administrator
West 2nd and Lincoln
Elk City, Oklahoma 73644

Gentlemen:

This is in reference to your request for a byproduct material license in the name of Community Hospital. In order for us to complete our review of your request, please supply the following:

1. You did not specify the revision number and date requested at the top of page 2 on Form NRC-313M. The correct reference is: Regulatory Guide 10.8, Revision 1, October 1980. Amend and resubmit for NRC staff review this page of your application with correct reference.
2. In addition to the survey meter specified in your application, you should have an instrument with a high-level range capable of reading up to 1,000 mr/hr in order to measure radiation exposure rates that may exist in the vicinity of technetium-99m generators, etc. Specify the manufacturer's name, model number, and highest level range of the instrument in your laboratory that will fulfill this need.
3. You should amend your Medical Isotope Committee composition to conform to that of the Radiation Safety Committee specified in 10 CFR 35.11(b). The words "or designee" and the attendance requirements of the Radiation Safety Officer should be removed from the membership list. If the words "or designee" should remain on membership composition of the Medical Isotope Committee for administrative and nursing personnel, it should be clear that these designated members would be from the nursing and administrative staffs. Amend and resubmit your Radiation Safety Committee composition for NRC staff review.

We will continue our review of your application upon receipt of this information. Please reply in duplicate and refer to Control No. 460629.

Sincerely,

Original Signed By
Jack E. Whitten
Jack E. Whitten
Nuclear Materials
Safety Section

Enclosure:
Regulatory Guide 10.8

NMSS
JEW:whitten;df
6/11/85

C:NMSS
RJE:everett
6/12/85


8508210103 850708
REG4 LIC30
35-23180-01 PDR



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011



BETWEEN: William O. Miller, Chief
License Fee Management Branch
Office of Administration

R. J. Everett, Chief
Material Radiation Protection Section, TPB,
DV&TP, RIV

LICENSEE FEE TRANSMITTAL

A. REGION IV

1. APPLICATION ATTACHED

Applicant/Licensee:

Application Dated:

Control No.:

License No.:

Community Hosp.
April 29, 1985
460629
(030-28679)

2. FEE ATTACHED

Amount:

Check No.:

\$580-
13347

3. COMMENTS

Signed

Date

Laura Hurley
May 15, 1985

B. LICENSEE FEE MANAGEMENT BRANCH

1. Fee Category and Amount:

2. Correct Fee Paid. Application may be processed for:

Amendment

Renewal

License

7C \$580

 ✓

Signed

Date

Frances Brown
5/17/85

908
5/17/85