



DUKE POWER

October 31, 1996

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Oconee Nuclear Station Unit 1
Docket Nos. 50-269, -270, -287
Licensee Event Report 269/96-08, Revision 1
Problem Investigation Process No.: 0-096-1666

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 269/96-08, concerning a missed valve surveillance which resulted in borated water storage tank technical inoperability.

This is a supplemental report. It is being submitted in accordance with 10 CFR 50.73 (a) (2) (i) (B). This event is considered to be of no significance with respect to the health and safety of the public.

This report was originally reported as 269/96-10. Per guidelines in Nureg 1022, Revision 1, second draft, page 119, the sequential number for this report has been revised to 269/96-08.

Very truly yours,

B. W. Hampton for
J. W. Hampton

9611130115 961031
PDR ADOCK 05000269
S PDR

Attachment

1022
11

Document Control Desk
Date: October 31, 1996

cc: Mr. S.D. Ebnetter
Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

Mr. D. E. LaBarge
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Mr. M. A. Scott
NRC Resident Inspector
Oconee Nuclear Station