



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 409 838-6631

August 20, 1985


RBG-21903

File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station - Unit 1
Docket No. 50-458
Interim Report/DR-314



An interim or final status report on DR-314 concerning leakage of the fluid Fyrquel from pump seals to the pump drive motor in Lorg-Warner electrohydraulic operators for Copes-Vulcan modulating valves will be provided by September 6, 1985.

Sincerely,

for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

PJD
PJD/amg

cc: Director of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8508280082 850820
PDR ADOCK 05000458
S PDR

85-751

[227]
10