

APPENDIX A

Exo Sensors, Inc.
Docket No. 99901015/85-01

NOTICE OF VIOLATION

As a result of the inspection conducted on May 28-31, 1985, and in accordance with Section 206 of the Energy Reorganization Act of 1974 and its implementing regulation 10 CFR Part 21, the following violation was identified and categorized in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 49 FR 8583 (March 8, 1984):

Section 21.21 of 10 CFR Part 21, dated January 1, 1985 states, in part:
"Each individual, corporation ... subject to the regulations in this part shall adopt procedures to: (1) Provide for: (i) Evaluating deviations or (ii) informing the licensee or purchaser of the deviation..."

Contrary to the above, Exo Sensors did not have any Part 21 procedures at the time of the inspection. However, procedures were developed during the inspection and reviewed and found acceptable by the inspector.

This is a Severity Level V violation (Supplement VII).

8508280164 850826
PDR GA999 EMV*****
99901015 PDR