



Northeast
Utilities System

107 Selden Street, Berlin, CT 06037

Northeast Utilities Service Company
P.O. Box 270
Hartford, CT 06141-0270
(203) 665-5000

November 4, 1996

Docket No. 50-336
B15975

Re: 10 CFR 50.73(a)(2)(ii)(B)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

This letter forwards Licensee Event Report (LER) 96-031-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on October 3, 1996. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(ii)(B).

The following are NNECO's commitments made within this letter. All other statements made within this letter are for information only.

- B15975-01: The review and analysis of this event is continuing. Efforts are ongoing to reanalyze the peak secondary side pressure for a Single MSIV Closure Event. The reanalysis of the design basis event will resolve the conditions described in this LER. The consequences of these potentially non-conservative assumptions on other design basis events will also be reviewed. As a result of the reanalyses, appropriate corrective actions will be implemented prior to restart to ensure that the plant response to these events is adequate.
- B15975-02: A supplemental LER will be issued to provide the results of the reanalyses and the resultant corrective actions before March 1, 1997.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

P. M. Richardson
Director - Millstone Unit No. 2

9611130521 961104
PDR ADOCK 05000336
S PDR

cc: see page 2

IE221/

Attachment: LER 96-031-00

cc: H. J. Miller, Region I Administrator
D. P. Beaulieu, Resident Inspector, Millstone Unit No. 2
D. G. McDonald, Jr., NRC Project Manager, Millstone Unit No. 2