



NRC FORM 591 - PART 2  
(7-91)  
10 CFR 2.201

## SAFETY INSPECTION

Page 2 of 2

## 1. LICENSEE

Westward Seafoods, Inc.  
P.O. Box 920608  
Dutch Harbor, Alaska 99692

## 2. REGIONAL OFFICE

REGION V  
U S NUCLEAR REGULATORY COMMISSION  
1450 M'RIA LANE SUITE 210  
WALNUT CREEK CA 94596-5388

## 3. DOCKET NUMBER(S)

030 - 31874

## 4. LICENSE NUMBER(S)

50 - 29018 - 01

## 5. DATE OF INSPECTION

August 2, 1996

## 3. (Continued)

G.

H.

I.

☒ 4.

The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.

☒ A.

Contrary to 10 CFR 20.1101(c), the licensee's radiation safety program was not reviewed for content and implementation in 1994.

☒ B.

Contrary to License Condition 11.A and B., licensed material was used by or under the supervision of individuals and radiation Safety Officers who were not authorized by name on the license, and who had not completed the manufacturer's training program for gauge users.

☒ C.

The licensee's radiation survey meter was not calibrated at an annual frequency in 1991, 1993, 1994, and 1995, as required by License Condition 21.A. (Item 10.3 of application dated 8/14/90).