

AUG 26 1985

Docket: 030-10068

Morrison-Knudsen
ATTN: Bruce Peterson, RSO
400 Broadway
Boise, Idaho 83729

Gentlemen:

Enclosed for your records is Form NRC-591, "Safety Inspection." Please note that no violations were observed during the August 12, 1985.

Since Morrison-Knudsen has an active NRC Byproduct Material License, your activity will be assessed an inspection fee for this inspection as required by 10 CFR 170.12(g) although no activities had been conducted since the previous inspection of your NRC Byproduct Material License on November 29, 1983.

Please call if you have any questions concerning this matter.

Sincerely,

"Original Signed by,"

Russell Wise
Radiation Specialist

Enclosure:
Form NRC-591

cc:
Idaho Radiation Control Program Director

bcc:
DMB - Original (IE-07)
RMartin
RBangart
D. Weiss, LFMB (AR-2015)
*Inspector
*MIS System
*RIV Files
*NMSS
*RSTS Operator (close report)

* w/766

RIV:NMSS *pw*
RWeiss;ap
8/22/85

C:NMSS
Everett
8/23/85

pbh
C:R&SPB
REHall
8/26/85

8509030228 850826
REG4 LIC30
11-15946-01 PDR

IE 07
11