

AUG 26 1985

Docket: 030-05169

Exxon Company, U.S.A.
ATTN: Michael E. Ervin, RSO
P.O. Box 1163
Billings, Montana 59103

Gentlemen:

Enclosed for your records is Form NRC-591, "Safety Inspection." Please note that no violations were observed during the August 15, 1985.

Since Exxon Company, Billings Refinery has an active NRC Byproduct Material License, your activity will be assessed an inspection fee for this inspection as required by 10 CFR 170.12(g) although no activities had been conducted since the previous inspection of your NRC byproduct Material License on July 10, 1984.

Please call if you have any questions concerning this matter.

Sincerely,

"Original Signed by:"

Russell Wise
Radiation Specialist

Enclosure:
Form NRC-591

cc:
Montana Radiation Control Program Director

bcc:
DMB - Original (IE-07)
RMartin
RBangart
D. Weiss, LFMB (AR-2015)
*Inspector
*MIS System
*RIV Files
*NMSS
*RSTS Operator (close report)

* w/766

8509030269 850826
REG4 LIC30
25-03375-02 PDR

RIV:NMSS *pu*
R Wise;ap
8/22/85

C:NMSS *ly*
RLEverett
8/23/85

pu
C:R&SPB
REHall
8/26/85

I E07
11