

ILLINOIS POWER COMPANY

U-600240
L14-85(08-23)-L
1A.120

CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727

August 23, 1985

Docket No. 50-461

Mr. James G. Keppler
NRC Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 61037

Subject: Potential 10CFR50.55(e) Deficiency 55-85-05:
Inadequate Design Change Control by Zack Company

Dear Mr. Keppler:

In Illinois Power Company letter dated June 10, 1985, (Ref: letter D. P. Hall to J. G. Keppler, U-600150), your office was provided an interim report addressing the status of the subject 10CFR50.55(e) investigation. It was anticipated at the time that a final report would be provided in approximately sixty (60) days.

Sargent & Lundy has required additional time to perform a review of this issue and complete the safety significance evaluation. It is anticipated that approximately thirty (30) additional days will be necessary to complete this review, determine reportability and provide a final report on the issue.

If you have any questions or comments regarding the status of actions taken on this issue, please contact Illinois Power Company.

Sincerely yours,

D. P. Hall
Vice President

RLC/kaf

cc: NRC Resident Office
Director - Office of I&E, USNRC, Washington, DC 20555
Illinois Department of Nuclear Safety
INPO Records Center

8509030521 850823
PDR ADOCK 05000461
S PDR

AUG 27 1985

IE27

1/0

EE37