



CONNECTICUT YANKEE ATOMIC POWER COMPANY

TELEPHONE  
203-665-5000

BERLIN, CONNECTICUT  
P.O. BOX 270 HARTFORD, CONNECTICUT 06141-0270

August 28, 1985

Docket No. 50-213  
B11656

Director of Nuclear Reactor Regulation  
Attn: Mr. John A. Zwolinski  
Operating Reactors Branch #5  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Reference: (1) J. F. Opeka letter to J. A. Zwolinski, dated May 10, 1985.

Gentlemen:

Haddam Neck Plant  
Clarification of Proposed Revision to Technical Specifications

In Reference (1) revisions to Technical Specification 3.13, Refueling, were proposed to ensure the assumptions and initial conditions of the reactor cavity seal failure safety analysis were met. Through discussions with the NRC Haddam Neck Project Manager, it was pointed out that confusion exists over what was meant by the 2nd sentence within the 2nd paragraph of proposed Specification 3.13.C(1). In order to clarify that the location the fuel is returned to is the reactor core and not literally "to the bottom of the reactor pressure vessel", as stated in Reference (1), we propose that sentence be revised as shown in Attachment (1).

Very truly yours,

CONNECTICUT YANKEE ATOMIC POWER COMPANY

J. F. Opeka  
Senior Vice President

By: C.F. Sears  
Vice President

8509040093 850828  
PDR ADOCK 05000213  
P PDR

Asal  
1/1