




GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775

AREA CODE 504 635-6094 346-8651

July 26, 1985
RBG- 21705
File Nos. G9.5, G15.4.1

Mr. Robert D. Martin, Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Martin:

River Bend Station - Unit 1
Refer to: Region IV
Docket No 50-458/Report 85-33

This letter is in response to the Notice of Violation contained in NRC I&E Inspection Report No. 50-458/85-33. The inspection was performed by Messrs. L. D. Gilbert and W. M. McNeill during the period April 15 - June 27, 1985, of activities authorized by NRC Construction Permit CPPR-145 for River Bend Station Unit No. 1.

Gulf States Utilities Company's (GSU's) response to the Notice of Violation 85-33-01, "Inspection Records," is provided in the enclosed attachment. This completes GSU's response to the Notice of Violation.

Sincerely,

J. C. Daddens
Vice President
River Bend Nuclear Group

PJD
JCD/TCC/PJD/ang

Attachment

8509040147 850828
PDR ADOCK 05000458
G PDR

IC-102/85

ATTACHMENT

July 26, 1985
RBG- 21705

Response to Notice of Violation

Reference

Notice of Violation - E. H. Johnson letter to W. J. Cahill, dated July 12, 1985.

Refer to Docket 50-458/85-33.

Response to 85-33-01 Inspection Reports

Reason for the Violation

This violation resulted from the failure of the Inspection Report (IR) reviewer to obtain concurrence of the originating inspector for a change which affected inspection results. Alternately, the reviewer could have either performed and documented a verification inspection or justified the change on the IR, but he did not do so.

Correction of inspection documentation which does not affect inspection results is normally accomplished by the reviewer without further approvals.

Corrective Steps Which Have Been Taken and Results Achieved

Type "C" IR P-5700083 was issued to cause all inspection disciplines to review a sample of their IR's for similar occurrences. Of the 1462 IR's reviewed by the other disciplines, no instance was found where results were changed by the reviewer without documented justification.

For the As-Built discipline where the original finding was observed, 100% of the IR's were reviewed (approximately 1000). This review identified five additional IR's which were changed by the reviewer and could not be justified. Reinspection of the affected supports for the changed attribute listed on these five IR's revealed four to be acceptable and one unacceptable. Unsatisfactory IR W5200677 was issued for this support.

Corrective Steps Which Will Be Taken To Avoid Further Violations

Documented retraining has been given to all SWEC inspection personnel authorized to perform review of Inspection Documentation. Instruction was given on the proper methods to be employed for corrections and/or changes to Inspection Documentation.

Date When Full Compliance Was Achieved

Full compliance was achieved July 11, 1985.


UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

STATE OF LOUISIANA	§	
PARISH OF WEST FELICIANA	§	
In the Matter of	§	Docket Nos. 50-458
GULF STATES UTILITIES COMPANY	§	50-459

(River Bend Station,
Unit 1)


AFFIDAVIT

J. C. Deddens, being duly sworn, states that he is a Vice President of Gulf States Utilities Company; that he is authorized on the part of said Company to sign and file with the Nuclear Regulatory Commission the documents attached hereto; and that all such documents are true and correct to the best of his knowledge, information and belief.



J. C. Deddens

Subscribed and sworn to before me, a Notary Public in and for the State and Parish above named, this 26th day of July, 19 85.



Joan W. Middlebrooks
Notary Public in and for
West Feliciana Parish,
Louisiana

My Commission is for Life.