



Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038-0236

Nuclear Business Unit

NOV 20 1996

LR-N96385

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Dear Sir:

HOPE CREEK GENERATING STATION
DOCKET NO. 50-354
UNIT NO. 1
LICENSEE EVENT REPORT NO. 95-033-12

This Licensee Event Report supplement entitled "Technical Specification Surveillance Requirement Implementation Deficiencies" is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(i)(B).

This supplement documents the discovery of a Technical Specification surveillance implementation deficiency identified by the Technical Specification Surveillance Improvement Program (TSSIP). As stated in LER 354/95-033-01, additional Technical Specification surveillance implementation deficiencies discovered by TSSIP with minimal safety significance will be documented in supplements to this LER until completion of the TSSIP project.

Sincerely,

Mark Bezilla
General Manager,
Hope Creek Operations

JWK/mrh
SORC Mtg. 96-109

C Distribution
LER File

9611270159 961120
PDR ADOCK 05000354
S PDR

The power is in your hands.