



**Florida
Power**

CORPORATION
Crystal River Unit 3
Docket No. 50-302

November 20, 1996
3F1196-11

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555-0001

Subject: Licensee Event Report (LER) 94-009-02

Dear Sir:

Please find the enclosed Licensee Event Report (LER) 94-009-02 regarding unauthorized tests of Makeup Tank level/hydrogen pressure. The original LER described the unauthorized test which occurred on September 5, 1994 while Supplement 1 to the LER described other concerns related to operating curve changes and reviews of calculations that occurred or were discovered subsequent to the original event. This supplement identifies a similar unauthorized test discovered to have been performed on September 4, 1994, incorporates the root causes of the related concerns along with associated corrective actions, and provides an update to previously described actions. These corrective actions have been previously communicated to NRC via FPC Letter 3F0996-01 dated September 9, 1996 in reference to NRC Report No. 50-302/EA 95-126.

This supplemental report is submitted by Florida Power Corporation in accordance with 10 CFR 50.73

Sincerely,

P.M. Beard, Jr.
Senior Vice President
Nuclear Operations

TWC/

Attachment

xc: Regional Administrator, Region II
Project Manager, NRR
Senior Resident Inspector

9611270173 961120
PDR ADOCK 05000302
S PDR

IE221