

SAFETY INSPECTION

Page 1 of 2

1. LICENSEE

IDAHO STATE UNIVERSITY
TECHNICAL SAFETY OFFICE
Box 8016
POCATELLO, IDAHO 83209

2. REGIONAL OFFICE

REGION IV
U S NUCLEAR REGULATORY COMMISSION
611 RYAN PLAZA DRIVE SUITE 400
ARLINGTON TX 76011-8064

3. DOCKET NUMBER(S)

030-32322/96-01

4. LICENSE NUMBER(S)

11-27380-01

5. DATE OF INSPECTION

10/24-25/96

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

☐ 1. Within the scope of this inspection, no violations were observed.

☐ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.

☒ 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.11.

☐ A. _____ was not properly posted to indicate the presence of a _____, 10 CFR 20.203(b),(c),(d),(e) or 34.42.

☒ B. LEAK TESTS OF 3 SEALED SOURCES were not performed at the proper frequencies. 10 CFR _____ or License Condition Number 13.

☐ C. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____.

☐ D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.

☐ E. Reports or notification of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.

☒ F. ON 10/23/95, 23 SOURCES USING MORE THAN 30 ALI (5.1mCi) OF I-125 WAS NOT SURVEYED AT THE END OF THE DAY OF USE, LICENSE CONDITION 26 AND SECTION 10.6, PAGE 31, OF APPLICATION DATED 9/20/94

9611290141 961025
PDR ADOCK 03032322
C PDR

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE

DATE

SIGNATURE - NRC INSPECTOR

DATE

William L. Larson

10/25/96

William Radcliffe

10/25/96

SAFETY INSPECTION

Page 2 of 2

1. LICENSEE

IDAHO STATE UNIVERSITY
TECHNICAL SAFETY OFFICE
Box 8016
POCATELLO, IDAHO 83209

2. REGIONAL OFFICE

REGION IV
U S NUCLEAR REGULATORY COMMISSION
611 RYAN PLAZA DRIVE SUITE 400
ARLINGTON TX 76011-8064

3. DOCKET NUMBER(S)

030/32322/96-01

4. LICENSE NUMBER(S)

11-27380-01

5. DATE OF INSPECTION

10/24-25/96

3. (Continued)

☒ G.

A DOT TYPE A PACKAGE CONTAINING 40 mCi OF AM-241 WAS NOT MARKED AS A REPORTABLE QUANTITY WHEN TRANSPORTED ON PUBLIC ROADS THE WEEK OF 10/14/96. 10CFR 71.5 AND 49CFR 172.203(c)(2).

☒ H.

A DOT TYPE A PACK CONTAINING 8 mCi OF Cs-137 AND 40 mCi OF AM-241 WAS TRANSPORTED ON PUBLIC ROADS DURING THE WEEK OF 10/14/96 WITHOUT REQUIRED SHIPPING PAPERS. 10CFR 71.5 AND 49CFR 172.200 AND 49CFR 171.8

☒ I.

☒ 4.

The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.

☒ A.

BIOASSAY FOR P-32 used, conducted in 2/96, was conducted 9 weeks after ~~use~~ use instead of 4 weeks as required by license condition 26 and the application dated 9/20/94.

☐ B.

☐ C.