



**KERR-MCGEE** *W. J. Shelley* CORPORATION

KERR-MCGEE CENTER • OKLAHOMA CITY, OKLAHOMA 73125

May 25, 1976

Glen D. Brown, Chief  
Fuel Facility and Material Safety Branch  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

Re: License No. SUB-986  
Docket No. 40-8006

Dear Mr. Brown:

Please refer to your letter of May 13, 1976, transmitting the findings of your inspection conducted by Mr. Claude M. Wiblin on May 6, 1976.

Corrective action has been taken as follows:

1. The five test pits which were unlocked at the time of the inspection have been equipped with steel covers, locked in place. This required condition has been placed on our inspection schedule and will be policed in the future.
2. The signs bearing the words: "Caution Radioactive Materials" were replaced on all test pits on May 10, 1976. Inspection of the signs has been added to our inspection schedule. Signs will be replaced periodically as required by weathering.

Should you need additional information, please let me know.

Sincerely yours,

*W. J. Shelley*  
W. J. Shelley, Director  
Regulation and Control

WJS:ml



**KERR-McGEE** COMPANY

KERR-McGEE CENTER • OKLAHOMA CITY, OKLAHOMA 73125

May 25, 1976

Glen D. Brown, Chief  
Fuel Facility and Material Safety Branch  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

Re: License No. SUB-986  
Docket No. 40-8006

Dear Mr. Brown:


Please refer to your letter of May 13, 1976, transmitting the findings of your inspection conducted by Mr. Claude M. Wiblin on May 6, 1976.

Corrective action has been taken as follows:

1. The five test pits which were unlocked at the time of the inspection have been equipped with steel covers, locked in place. This required condition has been placed on our inspection schedule and will be policed in the future.
2. The signs bearing the words: "Caution Radioactive Materials" were replaced on all test pits on May 10, 1976. Inspection of the signs has been added to our inspection schedule. Signs will be replaced periodically as required by weathering.

Should you need additional information, please let me know.

Sincerely yours,

  
W. J. Shelley, Director  
Regulation and Control

WJS:ml



**KERR-McGEE** CORPORATION

KERR-McGEE CENTER • OKLAHOMA CITY, OKLAHOMA 73125

May 25, 1976

Glen D. Brown, Chief  
Fuel Facility and Material Safety Branch  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

Re: License No. SUB-986  
Docket No. 40-8006

Dear Mr. Brown:


Please refer to your letter of May 13, 1976, transmitting the findings of your inspection conducted by Mr. Claude M. Wiblin on May 6, 1976.

Corrective action has been taken as follows:

1. The five test pits which were unlocked at the time of the inspection have been equipped with steel covers, locked in place. This required condition has been placed on our inspection schedule and will be policed in the future.
2. The signs bearing the words: "Caution Radioactive Materials" were replaced on all test pits on May 10, 1976. Inspection of the signs has been added to our inspection schedule. Signs will be replaced periodically as required by weathering.

Should you need additional information, please let me know.

Sincerely yours,

  
W. J. Shelley, Director  
Regulation and Control

WJS:ml