

APPENDIX A

NOTICE OF VIOLATION

Borg-Warner Corporation
York Division
York, Pennsylvania

Docket No. 30-11712
License No. 37-16828-01

As a result of the inspection conducted on June 27, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

Condition 12.C of License No. 37-16828-01 requires that sealed sources authorized for a use other than radiography be leak tested as radiography sources in accordance with Section 34.25 of 10 CFR 34.

10 CFR 34.25 requires that such sources be leak tested at six (6) month intervals.

Contrary to the above, as of June 27, 1985, a 15.8 millicurie Co-60 survey instrument calibration check source was last leak tested on June 6, 1984, a period greater than (6) months.

This is a severity Level IV Violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Borg-Warner Corporation, York Division is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.