



ABB Electro-Mechanics  
New Britain, Connecticut 06051

QAM 201

SHEET 1 CON'T ON 2

REVISION DATE: 11/25/96

## QUALITY ASSURANCE MANUAL

### QAM 201

APPROVED /s/Peter A. Ferwerda  
QUALITY ASSURANCE MANAGER

DATE 4/2/90

APPROVED /s/J. W. Davis  
DIRECTOR OF OPERATIONS

DATE 4/2/90

9612040248 961126  
PDR GA999 EMVC-E  
99901297 PDR




REVISION DATE: 11/25/96

SHEET 2 CON'T ON 3

## TABLE OF CONTENTS

<u>TAB NO.</u>	<u>REV. DATE</u>	<u>TITLE</u>	<u>QAP NO.</u>
1	6/3/96	Introduction	QAP 200
2	6/3/96	Organization	QAP 201
3	6/3/96	Quality Assurance Program	QAP 202
4	6/3/96	Design Control	QAP 203
5	6/3/96	Procurement Document Control	QAP 204
6	6/3/96	Instructions, Procedures and Drawings	QAP 205
7	6/3/96	Document Control	QAP 206
8	6/3/96	Control of Purchased Material, Equipment and Services	QAP 207
9	6/3/96	Identification of Materials, Parts and Components	QAP 208
10	6/3/96	Control of Special Processes	QAP 209
11	6/3/96	Inspection	QAP 210
12	6/3/96	Test Control	QAP 211
13	6/3/96	Control of Test and Measuring Equipment	QAP 212
14	6/3/96	Handling, Storage and Shipping	QAP 213
15	11/25/96	Inspection, Test and Operating Status	QAP 214
16	6/3/96	Non-Conforming Items	QAP 215
17	6/3/96	Corrective Action	QAP 216
18	6/3/96	Quality Assurance Records	QAP 217
19	6/3/96	Audits	QAP 218
20	6/3/96	Customer Furnished Material	QAP 219



## TABLE OF CONTENTS

<u>TAB NO.</u>	<u>REV. DATE</u>	<u>TITLE</u>	<u>QAP NO</u>
21	6/3/96	Work Orders	QAP 220
22	6/3/96	Problem Disposition Reports	QAP 221
23	6/3/96	Indoctrination and Training	QAP 222
24	6/3/96	Calibration of Test and Measuring Equipment	QAP 223
25	6/3/96	Testing	QAP 224
26	6/3/96	Use of Drawing and Part Numbers	QAP 225
27	6/3/96	Engineering Change Orders	QAP 226
28	6/3/96	Sampling Plans	227
29	6/3/96	Authorized Equivalent or Substitute Items	228
30	6/3/96	Certificates of Conformance	QAP 229
31	6/3/96	Qualification of Inspection/Test Personnel	QAP 232
32	6/3/96	Qualification of Audit Personnel	QAP 233
33	6/3/96	Use of Outside Personnel	QAP 235
34	6/3/96	Quality Records (Documentation) Review	QAP 237