

sperry-sun
DRILLING SERVICES

3 December, 1996

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C., 20555

Re: Reply to a Notice of Violation
USNRC License # 42-26844-01
Docket No. 030-29470

Dear Sirs,

We are in receipt of the NRC Inspection 030-29470/96-01 and Notice of Violation dated 22 October, 1996. We appreciate the 15 day extension provided to us by Richard A. Leonardi, Jr. of USNRC Region IV office since we were not able to respond to this notice of violation within the required 30 day time period.

The notice of violation states:

10CFR 39.13(d) requires, in part, that an applicant establish and submit to the Commission its program for annual inspections of on-the-job performance of each logging supervisor.

License Condition 15 incorporates the inspection program containing the requirements of 10 CFR 39.13(d) as submitted in the licensee's application dated January 31, 1994.

Contrary to the above, as of September 23, 1996, job performance inspections for two logging supervisors who had worked at the Deadhorse, Alaska, facility had not been performed for calendar year 1995.

The violation occurred as a result of the District Management failing to allow time for consistently performing the Radiation Safety Program responsibilities of the annual inspections of on-the-job performance of each logging supervisors as required by 10CFR 39.13(d) and the License Condition 15.

The Corrective Action to address the violation was discussed with both the District Manager and District Radiation Safety Officer. They have assured me that all logging supervisors who do not have a current annual field inspection will have one performed in the very near future if it has not already been done. I have already received evidence of this being performed and these have been placed in the respective personnel files and are available for inspection.

9612050025 961203
PDR ADOCK 03029470
C PDR

3000 North Sam Houston Pkwy. East (77032) • P.O. Box 60070 • Houston, Texas 77205
(713) 987-5100 • Telex 6868761 • Fax (713) 987-4269

050003

A Dresser Industries, Inc. Company

1/0
Lept

Reply to a Notice of Violation

3 December, 1996

Page 2 of 3


The corrective action to avoid further violations of this type will consist of written discussion of this violation with a written certification of understanding by the District Manager and District Radiation Safety Officer on the following:

1. The requirements of the annual field inspection requirements.
2. This violation.
3. The consequences on failure to meet these requirements.

We expect full compliance with the annual field inspection requirements by 31 December, 1996.

Please call Richard Arsenault at (281) 871-4144 if you have any questions.

Respectfully,



Richard L. Arsenault, CSP
Radiation Safety Director
Manager, Compliance Assurance - Worldwide
Sperry-Sun Drilling Services, Inc.

cc: R. Clark
M. Kohlhauff
NRC License File
USNRC Region IV Office