



Public Service


2420 W. 26th Avenue, Suite 100D, Denver, Colorado 80211

Public Service
Company of Colorado
P.O. Box 840
Denver, CO 80201-0840
(303) 571-7511

August 30, 1985
Fort St. Vrain
Unit No. 1
P-85307

Regional Administrator
Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Attn: Mr. Dorwin Hunter



Docket No. 50-267

SUBJECT: 10CFR50.49 Environmental
Qualification of Electrical
Equipment Important to
Safety for Nuclear Power
Plants

REFERENCE: PSC letter dated 3/28/85
Warembourg to Johnson (P-85112)

Dear Mr. Hunter:

In the referenced letter, PSC committed to revising the appropriate Emergency Procedures to provide a clearer course of action for the operator during a steam line break. To increase operator awareness of actions required following a major steam line rupture, PSC has given all operators specific training on the detailed actions required to assure break isolation within the four minutes designated in the Fort St. Vrain licensing basis. Due to additional items being pursued in our environmental qualification program (e.g. a new Steam Pipe Rupture Detection System), we anticipate future revisions to the Emergency Procedures. We conclude that procedure revisions at this time will cause more confusion than clarity for the operators. We are therefore deferring the revisions discussed in the referenced letter to coincide with our final environmental qualification program documentation. The schedule for these actions will be included with future correspondence.

8509160173 850830
PDR ADOCK 05000267
F PDR

85-806

H005
Return original
to RIV
1/0

If you have any questions, please contact Mr. M. H. Holmes at (303) 571-8409.

Very truly yours,

D. W. Warembourg
D. W. Warembourg, Manager
Nuclear Engineering Division

DWW/FT/km