

(12-81)  
10 CFR 2.201

## SAFETY INSPECTION

## 1. LICENSEE

St. John's Regional Medical Center  
2727 McClelland Boulevard  
Joplin, MO 64801

## 2. REGIONAL OFFICE

U.S. NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, IL 60137

## 3. DOCKET NUMBER(S)

030-12728  
030-00308

## 4. LICENSE NUMBER(S)

24-01090-03  
24-01090-02

## 5. DATE OF INSPECTION

August 22, 1985

## Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☐ 1. Within the scope of this inspection, no violations were observed.
- ☐ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- ☒ 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.  
THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.
- ☐ A. \_\_\_\_\_ was not properly posted to indicate the presence of a \_\_\_\_\_, 10 CFR 20.203(b), (c), (d), (e) or 34.42.
- ☐ B. Containers located in \_\_\_\_\_ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).
- ☐ C. \_\_\_\_\_ of sealed sources were not performed at the proper frequencies. 10 CFR \_\_\_\_\_ License Condition Number \_\_\_\_\_.
- ☒ D. Records of surveys performed of cesium-137 implant patients were not properly maintained.  
~~XXXX~~ \_\_\_\_\_ or License Condition Number 17 (License Number 24-01090-03)
- ☐ E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
- ☐ F. Reports or notifications of \_\_\_\_\_ were not made in accordance with 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
- ☒ H. Records of the Radiation Safety Committee meetings were not properly maintained.  
License Condition Number 17 (License Number 24-01090-03).
- ☒ I. Records of the linearity tests on the dose calibrator were not properly maintained.  
License Condition Number 17 (License Number 24-01090-03).
- ☒ J. The physicist working with the cesium-137 brachytherapy sources did not have an extremity badge. License Condition Number 17. (License Number 24-01090-03).
- ☐ K. \_\_\_\_\_  
8509160380 850903  
REG3 LIC30 PDR  
24-01090-02

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE

DATE

SIGNATURE - NRC INSPECTOR

DATE

SEP 9 1985