

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

FEB 18 2020

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC ~~20555-0001~~ 20852


Serial No. 20-057
SPS-LIC/JWD R0
Docket No. 50-280
License No. DPR-32

VIRGINIA ELECTRIC AND POWER COMPANY
SURRY POWER STATION UNIT 1
INSERVICE INSPECTION OWNER'S ACTIVITY REPORT (OAR)

In accordance with the requirements of ASME Code Case N-532-5, Virginia Electric and Power Company (Dominion Energy Virginia) hereby submits the Inservice Inspection Owner's Activity Report (Form OAR-1) for Surry Unit 1 refueling outage S1R29, which ended on November 29, 2019. This document contains the reporting requirements for the second refueling outage of the second period in the fifth ten-year inservice inspection interval for Surry Unit 1.

If you have any questions concerning this information, please contact Mr. Jacob Dietrich at (757) 365-2161.

Very truly yours,



David Wilson
Director Station Safety & Licensing
Surry Power Station

Attachment: Owner's Activity Report (Form OAR-1), Surry Unit 1 Refueling Outage S1R29, Second Period of the Fifth ISI Interval

Commitments made in this letter: None

A047
NRR

cc: U.S. Nuclear Regulatory Commission
Region II
Marquis One Tower
245 Peachtree Center Avenue NE
Suite 1200
Atlanta, Georgia 30303-1257

NRC Senior Resident Inspector
Surry Power Station

Mr. V. Thomas
NRC Project Manager – Surry
U. S. Nuclear Regulatory Commission
One White Flint North
Mail Stop 08 G9A
11555 Rockville Pike
Rockville, Maryland 20852-2738

Mr. E. Miller
NRC Senior Project Manager – North Anna
U.S. Nuclear Regulatory Commission
One White Flint North
Mail Stop 08 G-9A
11555 Rockville Pike
Rockville, MD 20852-2738

Mr. R. A. Smith
Authorized Nuclear Inspector
Surry Power Station

Serial No.: 20-057
Docket No.: 50-280

ATTACHMENT

**OWNER'S ACTIVITY REPORT (FORM OAR-1),
SURRY UNIT 1 REFUELING OUTAGE S1R29,
SECOND PERIOD OF THE FIFTH ISI INTERVAL**

**VIRGINIA ELECTRIC AND POWER COMPANY
(DOMINION ENERGY VIRGINIA)**

CASES OF ASME BOILER AND PRESSURE VESSEL CODE

FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number 1-5-2-2 (Unit 1, 5th Interval, 2nd Period, 2nd Report)Plant Surry Power Station, 5570 Hog Island Road, Surry, VA 23883Unit No. 1 Commercial service date 12/22/1972 Refueling outage no. S1R29
(if applicable)Current inspection interval 5th
(1st, 2nd, 3rd, 4th, other)Current inspection period 2nd
(1st, 2nd, 3rd)Edition and Addenda of Section XI applicable to the inspection plans 2004 EditionDate and revision of inspection plans Surry Unit 1, 5th Interval ISI Plan, Revision 4 May, 2019Edition and Addenda of Section XI applicable to repair/replacement activities, if different than the inspection plans N/ACode Cases used for inspection and evaluation: See Surry Unit 1, 5th Int. ISI Plan, Rev. 4 Section 6 for complete list of code cases
(if applicable, including cases modified by Case N-532 and later revisions)

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of S1R29 conform to the requirements of Section XI. (refueling outage number)

Signed K. Mitchell / ISI Program Owner Date 2/13/2020
Owner or Owner's Designee, Title

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and employed by The Hartford Steam Boiler Inspection and Insurance Company of Connecticut have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

R. Smith Commissions NB-7933 NS, IS; VA883(R)
Inspector's Signature National Board, State, Province, and Endorsements

Date 2/13/2020

CASES OF ASME BOILER AND PRESSURE VESSEL CODE
FORM OAR-1 OWNER'S ACTIVITY REPORTCASE
N-532-5**Table 1****Items with Flaws or Relevant Conditions That Required Evaluation for Continued Service**

Examination Category and Item Number	Item Description	Evaluation Description
	None	

FORM OAR-1 OWNER'S ACTIVITY REPORT

Table 2
Abstract of Repair/replacement Activities Required for Continued Service

Code Class	Item Description	Description of Work	Date Completed	Repair/Replacement Plan Number
1	01-RC-PP-2.00-RC-PIPE-200-1502	Hanger 1 hardware, replacement of fasteners	11/23/2019	2019-132
3	01-CC-E-1C-HTEXCH	Piping Replacement, through wall leak	11/26/2019	2019-135
3	01-CC-E-1D-HTEXCH	Piping replacement, through wall leak	11/21/2019	2019-122
3	01-SW-PP-30.00-WS-PIPE-24-10	Through wall indication directly upstream of 1-SW-MOV-103A inlet flange	11/6/2019	2019-101