

TIMKEN

THE TIMKEN COMPANY

GENERAL OFFICES
CANTON, OHIO, U.S.A. 44706
TELEPHONE: (216) 438-3000

July 11, 1985

RECEIVED

'85 AUG -1 AIO:11

NUCLEAR REGULATORY COMMISSION
Material Licensing Section
799 Roosevelt Road
Glen Ellyn, IL 60137

U.S. N.R.C.
LIC. FEE MGMT. BRANCH

Gentlemen:

Reference: NRC License No. 34-15207-02 dated April 25, 1985

We request an amendment to the referenced license to increase the number of sources permitted from four to six. These sources are to be mounted in identical source housings as are the present ones (Kay-Ray Model 7060SD).

These units are mounted on our continuous caster which has four strands. Being production equipment, we cannot afford to be without the level control functions provided by these units. We desire to purchase one to two spare units to be used in the event of malfunction or damage to an on-line source housing.

These units would be stored in our locked security area as described and shown in our license No. 34-15207-01, amendment No. 06, dated January 14, 1985. If the spare unit is needed on the caster, Kay-Ray personnel would be called in to install, leak test, and calibrate the unit.

If there are further questions on this request please contact our office.

Prepared by:

Applicant	<i>Cay</i>
Check No.	<i>752009</i>
Amount Fee Category	<i>\$60</i>
1. License Fee	<i>3. P. and</i>
Date Check Rec'd	<i>8/1/85</i>
Received By	<i>[Signature]</i>

H. Roger Hockenberry
H. Roger Hockenberry
Radiation Safety Officer
(216) 438-3292

Certifying Officer:

R. M. Chapis
R. M. Chapis
Director - Legal Services

RECEIVED
JUL 22 1985
REGION III

dml

8508220235 850726
REG3 LIC30
34-15207-02 PDR

CONTROL NO. 7 937 7

JUL 22 1985