

T4  
0114

# RADIATION PROTECTION CONSULTANTS, LTD.



Serving Radiology, Nuclear Medicine, Therapy and Industrial Facilities Since 1968

4255 WESTBROOK DRIVE, SUITE 211  
AURORA, ILLINOIS 60505  
PHONE: (312) 369-6488  
PHONE: (312) 851-5986

February 8, 1985

James W. Patterson  
Material Licensing Branch  
Division of Fuel Cycle and Material Safety  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. Patterson:

Reference: 77409

We are in receipt of your letter dated January 15, 1985 and submit the following information.

1. Enclosed please find a copy of the label which appears on the point of sale package.
2. The discrepancy between model numbers listed in Condition 10 of our current license and those listed in the reference letter of July 12, 1982 were apparently due to typographical errors which appeared on the NRC License. The model numbers contained in the reference letter dated July 12, 1982 are the correct model numbers.
3. Copies of the distribution reports for the periods of 1983 and 1984 were submitted at the required times for both of those years. Copies of those reports are included with this letter.
4. Should we desire to change our manufacturer of sources, we will apply for an appropriate amendment to our license.

The information contained in this letter has been submitted to you previously in letters dated September 25, and October 19, 1984. The first letter was addressed to Mrs. I. Myers and the second to yourself.

Should you have any additional questions or if we can provide any additional information for you, please contact me at your convenience.

Very truly yours,

Ronald D. Edwards  
for Rixson-Firemark, Inc.

8508220360 850725  
NMSS LIC30  
12-19060-02E PDR