

P. O. BOX 712 • MILWAUKEE, WISCONSIN 53201

FROEDTERT Malt Corporation

TELEPHONE: AREA CODE 414

671-1166

July 2, 1985

U.S. Nuclear Regulatory Commission, Region III
Materials Licensing Section
799 Roosevelt Road
Glen Ellyn, IL 60137

Re: Renewal of License Number 48-16638-01

Gentlemen:

Please be advised that Froedtert Malt Corporation, 3830 West Grant Street, Milwaukee, Wisconsin 53215, is requesting renewal of our License Number 48-16638-01 as amended. The expiration date is August 31, 1985. We wish to continue to operate under our current license.

See attached form NRC-374 and Wipe Test Kit results, two copies of each. Also attached is our check in the amount of \$150.00 made out to U.S. Nuclear Regulations Commission to cover the application fee.

We will continue to operate in accordance with these documents and applicable NRC regulations and license conditions.

Please direct your questions to Duane D. Strupp, Milwaukee Operations Manager, telephone number is 414-671-1166.

Sincerely,

8508220396 850725
REG3 LIC30
48-16638-01 PDR

RECEIVED

JUL 05 1985

REGION III

DDS:lo
Atts.

Applicant	<i>Froedtert Malt Corp.</i>
Check No.	<i>216638-01</i>
Amount / Fee	<i>\$150.00</i>
Type of Fee	<i>31. Rin</i>
Date Check Rec'd	<i>7/2/85</i>
Received By	<i>cap</i>

Duane D. Strupp

U.S. N.R.C.
MILWAUKEE
GRANT ST.

JUL 25 1985

RECEIVED

5 1985



CONTROL NO. 7 930 1

The Ohmart Corporation
4241 Allendorf Drive • Cincinnati, Ohio 45209
Phone (513) 272-0131 • TWX 810 461-2255

Froedtert Malt Corp
P. O. Box 712
Milwaukee, WI 53201

ATTN: D. D. Strupp



Wipe Test Kit

Kit No.	Date
1497	09-29-82
Customer P.O. No.	
66155	
FILE	

Caution: This kit is to be used only for the source holder described below. The information below appears on the metallic label on the actual OHMART source holder. Supply similar information if holder not OHMART.

S.O. No.	Isotope	Serial No.	m.C.I.	Source Holder
32386K	Cs-137	2538	35	2-HOUSE

Date Shipped	User Identification	Other
	FROEDTERT MALT	

Date of Test	Tested By (Tester's Signature)
10/15/82	NEW Strupp

This kit is to be used only by those whose license permit them to perform wipe tests. (Per CFR-10 Part 20)

OHMART ANALYSIS

The following are analysis results:

Source is OK	<input checked="" type="checkbox"/> (Activity less than 0.005 μ Ci)	<input type="checkbox"/> Rewipe Required	<input type="checkbox"/> Defective
--------------	---	--	------------------------------------

CPM: 52

R. Butler
Tested By/authorized Signat.

10-21-82
Date