




ms-15
T-2
(406) 442-2480 • 2475 Broadway, Helena, Montana 59601

May 29, 1985



C. L. Cain
Nuclear Materials Safety Section
United States Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Reference Control No: 17574

This information is in response to your letter dated April 26, 1985, requesting additional information.

1. Your assumption is correct.
2. The Radiation Safety Committee includes a member of St. Peter's Hospital management and Dr. Pedersen as Radiation Safety Officer.
3. The teletherapy unit is located in the Radiation Therapy Treatment room and has not been relocated since the last survey of November, 1981.
4. Your assumption is correct.
5. Enclosed is the emergency procedure.
6. Our leak tests are performed by Health Physics Associates, Limited, 304 Commercial Avenue, North Brook, Illinois 60062, using wipe test kit HPC-1. Their NRC license number is 12-09160-01.

Enclosed you will find results of the Safety Inspection performed May 2, 1984.

Thank you,

Duane Durkee

Duane Durkee
Radiology Department Head

Howard Purcell, Jr.
Howard Purcell, Jr.
Executive Director

8508300057 850626
REG4 LIC30
25-12453-03 PDR