



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

November 26, 1985

W3P85-3273
A4.05
QA

Director of Nuclear Reactor Regulation
Attention: Mr. G. W. Knighton
Licensing Branch No. 3
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Knighton:

Subject: Waterford 3 SES
Docket No. 50-382
License No. NPF-38
TEN YEAR INSERVICE INSPECTION PROGRAM, REVISION 1

Reference: Letter W3P85-1298 dated May 28, 1985

In accordance with 10CFR50.55(g), "Inservice Inspection Requirements", Louisiana Power & Light Company hereby submits seven (7) copies of Revision 1 of the Ten Year Inservice Inspection Program which is prepared in accordance with the ASME Code Section XI, 1980 Edition with Addenda through Winter 1981. Relief from the testing requirements of Section XI is requested when full compliance with the requirements of the code is not practical. In such cases, specific information is provided which identifies the applicable code requirements, justification for the relief request, and the testing method to be used as an alternative.

Revision 1 to the subject Inspection Program is being submitted at this time to include enhancements which were observed during field use of the program. The changes to this revision are described in the attachment to this letter, and there are change bars in the margin of the affected pages of this revision.


0512020522 051126
PDR ADOCK 05000382
G PDR

A047
1/6

Mr. G. W. Knighton
W3P85-3273
Page 2

It is hereby requested that the subject Program be approved and the ASME Section XI code relief requested be granted pursuant to Section 50.55(g)(6)(i) of 10CFR50.

Very truly yours,



K.W. Cook
Nuclear Support & Licensing Manager

KWC:BGM:sms

Enclosure

Attachment

cc (w/o enclosure): R.D. Martin, J.H. Wilson, NRC Resident Inspectors
Office, B.W. Churchill, W.M. Stevenson

ATTACHMENT

Major Changes contained in Revision 1
Ten Year Inservice Inspection Program

1. Added drawings to establish examination boundaries. Pages 31-44; 55-62; 74.
2. Reduced total number of bolting examinations from 40 to 20 due to determination that the deleted bolting was not pressure retaining. Page 22.
3. Determination of two safety valves having welded flanges. Page 26.
4. Changed total number of supports from 1429 to 1430. Page 73.
5. Added what examination figures apply to each code item on examination tables. Pages 14-16; 18-21; 23-26; 28; 48-50; 52; 53; 71; 73.



**LOUISIANA
POWER & LIGHT**

142 DELARONDE STREET
P O BOX 3008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

November 26, 1985

W3P85-3273
A4.05
QA

Director of Nuclear Reactor Regulation
Attention: Mr. G. W. Knighton
Licensing Branch No. 3
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Knighton:

Subject: Waterford 3 SES
Docket No. 50-382
License No. NPF-38
TEN YEAR INSERVICE INSPECTION PROGRAM, REVISION 1

Reference: Letter W3P85-1298 dated May 28, 1985


In accordance with 10CFR50.55(g), "Inservice Inspection Requirements", Louisiana Power & Light Company hereby submits seven (7) copies of Revision 1 of the Ten Year Inservice Inspection Program which is prepared in accordance with the ASME Code Section XI, 1980 Edition with Addenda through Winter 1981. Relief from the testing requirements of Section XI is requested when full compliance with the requirements of the code is not practical. In such cases, specific information is provided which identifies the applicable code requirements, justification for the relief request, and the testing method to be used as an alternative.

Revision 1 to the subject Inspection Program is being submitted at this time to include enhancements which were observed during field use of the program. The changes to this revision are described in the attachment to this letter, and there are change bars in the margin of the affected pages of this revision.

Mr. G. W. Knighton
W3P85-3273
Page 2

It is hereby requested that the subject Program be approved and the ASME Section XI code relief requested be granted pursuant to Section 50.55(g)(6)(i) of 10CFR50.

Very truly yours,

A handwritten signature in cursive script, appearing to read "K.W. Cook".

K.W. Cook
Nuclear Support & Licensing Manager

KWC:BGM:sms

Enclosure

Attachment

cc (w/o enclosure): R.D. Martin, J.H. Wilson, NRC Resident Inspectors
Office, B.W. Churchill, W.M. Stevenson

ATTACHMENT

Major Changes contained in Revision 1
Ten Year Inservice Inspection Program

1. Added drawings to establish examination boundaries. Pages 31-44; 55-62; 74.
2. Reduced total number of bolting examinations from 40 to 20 due to determination that the deleted bolting was not pressure retaining. Page 22.
3. Determination of two safety valves having welded flanges. Page 26.
4. Changed total number of supports from 1429 to 1430. Page 73.
5. Added what examination figures apply to each code item on examination tables. Pages 14-16; 18-21; 23-26; 28; 48-50; 52; 53; 71; 73.