

APPENDIX A
NOTICE OF VIOLATION

North American Inspection, Incorporated
Laurys Station, Pennsylvania

Docket No. 030-20982
License No. 37-23370-01

As a result of the inspection conducted on June 13, 14, and 26, 1985, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

1. 10 CFR 20.201(b) requires that each licensee make such surveys as may be necessary to comply with all sections of Part 20. As defined in 10 CFR 20.201(a), "survey" means an evaluation of the radiation hazards incident to the production, use, release, disposal, or presence of radioactive materials or other sources of radiation under a specific set of conditions.

Contrary to the above, surveys made outside the restricted area of the licensee's Laurys Station facility on June 8, 1985 were inadequate to assure compliance with 10 CFR 20.105(b), which limits radiation levels in unrestricted areas. Specifically, actual, accurate radiation measurements were not made; rather, apparently data were recorded which overestimated the distance from the source to the location where 2 mrem would be produced in one hour and thus did not represent the radiation levels that actually existed.

This is a Severity Level IV violation. (Supplement IV)

Pursuant to the provisions of 10 CFR 2.201, North American Inspection, Inc. is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8509130294 850909
REG1 LIC30
37-23370-01 PDR