



VIRGINIA POWER

September 6, 1985

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Mr. Ray R. Jenkins
Virginia Water Control Board
Piedmont Regional Office
2201 West Broad Street
Richmond, Virginia 23230

Surry Power Station - NPDES Permit Exception

Dear Mr. Jenkins:

This is to provide additional information concerning the NPDES permit exception at our Surry Power Station that was previously reported to you by phone on August 28, 1985.

At approximately 10:00 a.m. on August 28, 1985 station personnel noted that the flow recording pen for Outfall 011, the sewage treatment plant, was not responding to input voltage. It was determined that the failure was due to malfunctioning flow integrator parts. Replacement parts were ordered from the Fisher-Porter Company. Some of the parts have now been received, but some are still on order, and followup checks with Fisher-Porter have indicated a promise date of October 10, 1985 for the remaining parts. We will continue daily estimates of flow in the interim, using flow measuring equipment still in operation. Repairs will be made when the remaining parts are received.

If you have any questions regarding this exception, please do not hesitate to contact this department.

Very truly yours,

Michael G. Zadziora
B. M. Marshall
Manager
Water Quality

cc: Dr. J. Nelson Grace, USNRC - Docket Nos. 50-280/50-281
Mr. Harold R. Denton, USNRC - Docket Nos. 50-280/50-281 ✓
Mr. Donald J. Burke, USNRC - Docket Nos. 50-280-50-281

8509130375 850906
PDR ADOCK 05000280
S PDR

IE23
1/0