

ENCLOSURE

NOTICE OF VIOLATION

Department of Commerce

License No. 39-19222-01

The following violation was identified during an inspection conducted on January 7, 1986. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

License Condition 16(a) requires that each chromatograph detector containing Nickel 63 shall be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, a chromatograph detector containing Nickel 63, which had been in storage since April 1978, was used by the licensee in July and August 1985, and no leak test was performed prior to use.

This is a Severity Level IV violation (Supplement VI).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JAN 22 1986

B601290100 B60122
REG2 LIC30
39-19222-01 PDR