



**Northeast
Utilities System**

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791

March 31, 1997

Docket No. 50-245

B16359

Re: 10CFR50.73(a)(2)(i)
10CFR50.73(a)(2)(ii)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

This letter forwards supplemental Licensee Event Report (LER) 97-007-01, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 1 on January 31, 1997. This LER is submitted pursuant to 10CFR50.73(a)(2)(i) and 10CFR50.73(a)(2)(ii).

This supplemental report provides the cause of the event as well as the corrective action as committed to in Commitment No. B16238-1.

The following are Northeast Nuclear Energy Company's (NNECO's) commitments made within this letter. All other statements made within this letter are for information only.

- B16359-1 NNECO will enhance the design to provide an appropriate protective system for this transient prior to startup for operating Cycle 16.
- B16359-2 NNECO will review the existing QA/QC and Engineering Standards to ensure adequate review and processes are in place for in-house and purchased engineering activities prior to start up for operating Cycle 16.
- B16359-3 The current Supplemental Reload Licensing Submittal Analysis will be revised to require analysis for a loss of stator cooling initiated loss of feedwater heating event.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY



P. D. Hinnenkamp
Director, Unit Operations

1/1
Iezz

Attachment: LER 97-007-01

cc: Dr. W. D. Travers, Director, Special Projects
H. J. Miller, Region I Administrator

080136 S. Dembek, NRC Project Manager, Millstone Unit No. 1
T. A. Easlick, Senior Resident Inspector, Millstone Unit No. 1

9704080348 970331
PDR ADOCK 05000245
S PDR

