

JAMES C. MOSS
PRESIDENT

TULSA GAMMA RAY, INC.

1127 SOUTH LEWIS
TULSA, OKLAHOMA 74104
918/585-3228 FAX #918/584-5598

April 3, 1997

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Docket No. 30-12319
License No. 35-17178-01
EA-96-535

RE: Reply to a notice of violation.

1. Reason for Violation:

Radiation survey was not performed because the technician believed this function had been completed by another technician.

2. Corrective steps taken and results achieved:


Tulsa Gamma Ray employees have been instructed to perform a survey whenever walking into a vault whether or not they have unlocked or used the radioisotope that is stored in that facility. The results achieved are, no employees have been overexposed since implementing this instruction.

3. Corrective steps that will be taken to avoid further violations:

Employees will continue to survey the vault at the beginning of work shift.

4. Date of full compliance: November 21, 1996

Sincerely,


Peter J. Moss
President
Tulsa Gamma Ray, Inc.

JEOT
1/10

9704090053 970403
PDR ADOCK 03012319
C PDR

