


TEXAS UTILITIES GENERATING COMPANY  
SKYWAY TOWER • 400 NORTH OLIVE STREET, L.B. 81 • DALLAS, TEXAS 75201



WILLIAM G. COUNCIL  
EXECUTIVE VICE PRESIDENT

September 11, 1985  
TXX-4550

Mr. D.R. Hunter, Chief  
Reactor Project Branch 2  
U.S. Nuclear Regulatory Commission  
Office of Inspection & Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76012

Docket Nos.: 50-445  
50-446

COMANCHE PEAK STEAM ELECTRIC STATION  
PIPE SUPPORTS  
QA FILE: CP-85-28, SDAR-189  
FILE NO.: 10110

Dear Mr. Hunter:

On August 13, 1985 we verbally notified your Mr. S. Phillips of a deficiency regarding welding installation of tube steel members.

We have completed our investigation and concluded that the matter is not reportable under 10CFR50.55(e). Records supporting this determination are available for your inspector's review at the CPSES site.

Very truly yours,

*WG Council*

W.G. Council  
by D.R. Woodlan

*D Woodlan*

Licensing Supervisor

WGC:mlm

cc: NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

85-813  
8509190362 850911  
PDR ADOCK 05000445  
S PDR