



# Mercy Hospital

25 Church Street  
P.O. Box 650  
Wilkes-Barre, Pennsylvania 18765  
717-826-3100

August 23, 1985

John E. Glenn, Ph.D, Chief  
Nuclear Materials Safety Section B  
Division of Radiation Safety and Safeguards  
U.S. Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA 19406

Dear Dr. Glenn,

I make reference of your Docket No. 030-02971 in regard to the inspection of our facility of July 17, 1985. We will address your findings as they appear in your letter of August 9, 1985.

A. As required by condition 16 of our license:

1. The americium - 241 sealed source was leak tested and found to be free of removable contamination in excess of 0.005 uCi.
2. Our consultant physicist will leak test this sealed source each six (6) months and record the results.
3. Full compliance was completed on July 26, 1985.

B. As per condition 20 of our license:

1. Our Victoreen Model 491 G.M. survey meter has been sent to the Health Physics Associates Ltd. for recalibration.
2. We have purchased and received an additional GM survey meter Eberline Model E - 520 (serial No. 4169), to provide surveys while our Victoreen unit is out for its annual calibration.

RECEIVED-REGION I  
AUG 29 PM 1:52




8509190496 850917  
REG1 LIC30  
37-00897-01 PDR

A SISTERS OF MERCY HOSPITAL - PROVINCE OF SCRANTON

3. We currently have a calibrated survey meter within our department (Eberline Model E - 520). We expect the return of our calibrated Victoreen 491 unit from the Health Physics Associates Ltd. within the next few weeks.

Thank you for your time and consideration in this matter.

Sincerely,



W. David Keating  
Vice President, Ancillary Services

WDK/lr

Copies to: Robert Moylan, Executive Vice President  
Dr. S. M. Imperiale  
Jesse Waselus, Director, Radiology